NYC 9/11 Public Portal Document

New York State Department of Labor
Public Employee Safety and Health Bureau

Vehicle Contamination Sampling

SAMPLE # 1-17-02-#49-53

Vehicle Location or ID: Engine 22-Ladder 13 159 E. 85th St.

Vehicle Type: Engine 22 (Seagrave Pumper) - # SP9713

Asbestos

Sample Location of wipe:	Before vents turned on	After vents turned on
	___ Dashboard	___ Dashboard
	___ Front seat	___ Front seat
	___ Floor	___ Floor
	___ Back seat	___ Back seat
(49)	X Other: ceiling above windshield	X Other: blower unit near ceiling (rear of front cab) - 52

Metals

Sample Location of wipe:		
	X Dashboard - 50	___ Dashboard
	___ Front seat	___ Front seat
	___ Floor	X Floor - behind passenger side seat (53)
	___ Back seat	___ Back seat
	___ Other:	___ Other:

Other: Mercury

Sample Location of wipe:		
	___ Dashboard	___ Dashboard
	___ Front seat	___ Front seat
	X Floor - 51	___ Floor
	___ Back seat	___ Back seat
	___ Other:	___ Other:

At site initially
In-house decon

Sample Date: 1/17/02

Sampled By: M. Thorsland / C. Jay

NYC-WTC_000356366