NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 4/25/02
ADDRESS: 345 Chambers St., NY, NY 10282

RECEIVED
KAM CONSULTANTS
2002 APR 26 AM 9:06

T020426B

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	Pier #25									
1	North Exit of Stuyvesant H.S.	0700	1700	3	3	1800	1	1	40.00	0.0086
2	North west site	0801	1701	3	3	1800	0	0	< 20.00	< 0.0043

TECHNICIAN: D. SALIS
ROTAMETER: KAM101

CHAIN OF CUSTODY	
	FAX Results To NYC D.D.C

RECEIVED AT LAB BY: VN
SAMPLE CONDITION UPON RECEIPT: Good
DATE/TIME: 4/26/02

ANALYST: [signature] DATE RECEIVED: 4/26/02 DATE OF ANALYSIS 4/26/02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

04/25/2002 13:00 7187293774 KAM CONSULTANTS PAGE 01/01
CITY_21MC100_010394960
NYC-WTC_000357948