NYC 9/11 Public Portal Document

KAM
30-40 38th Street
Long Island City
New York, 11101
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTO) FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 2-12-02
ADDRESS: 345 Chambers St., NY, NY 10282

T020213A

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (str/mm²)	Structure Concentration (str/cc)
	PIER 25									
1	North Entrance of school - East	7:02	17:02	3	3	1800	0	0	<20.0	<0.0043
2	-11- — -11- — West	7:03	17:03	3	3	1800	0	0	<20.0	<0.0043

TECHNICIAN: Renata Dymkowska ROTAMETER: KAM101

CHAIN OF CUSTODY		
	FAX results to DDC.	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: ALEKS BARENBOYM DATE RECEVED: 2-13-02 DATE OF ANALYSIS 2-13-02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method
FAX RSULTS TO (212) 941-5356

PAGE 01/01
KAM CONSULTANTS
7187293774
02/13/2002 12:40
CITX_2INC100_01039504

NYC-WTC_000358024