NYC 9/11 Public Portal Document

35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTO[DY] FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 12/19/01
ADDRESS: 345 Chambers St., NY, NY 10282

T 0112 20 C

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION PIER #25	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	OUTSIDE NORTH - EAST ENTRANCE OF SCHOOL SIDE	16:01	23:58	3	3	1431	0	0	<1667	<[illegible]
2	↓ - WEST SIDE	16:02	23:59	3	3	1431	0	0	<1667	<[illegible]

RECEIVED
KAM CONSULTANTS
2001 DEC 20 PM 2:14

TECHNICIAN: A. MARTIROSSIAN
ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE FAX RESULTS TO NYC DDC	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: [signature] DATE RECEVED: 12/20 DATE OF ANALYSIS 12/20

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

PAGE 02/03 KAM CONSULTANTS 7187293774 12/20/2001 13:21

CITY_21MC100_010395212

NYC-WTC_000358167