NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTOL FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 12-20-01
ADDRESS: 345 Chambers St., NY, NY 10282

To 12-22

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER 25									
1	North Entrance of school - East	00.02	8.00	3	3	1434	0	0	< 16.67	< 0.004 f
2	-11- — -11- — West	00.03	8.01	3	3	1434	0	0	< 16.67	< 0.004 f

RECEIVED
KAM CONSULTANTS
2001 DEC 20 PM 8:45

TECHNICIAN: Renata Dymkowska ROTAMETER: KAM101

CHAIN OF CUSTODY	RECEIVED AT LAB BY: MC
FAX results to DDC.	SAMPLE CONDITION UPON RECEIPT:
	DATE/TIME: 12/20

ANALYST: DATE RECEVED: 12/20 DATE OF ANALYSIS 12/20

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method
FAX RSULTS TO (212) 941-5356

12/20/2001 13:21 7187293774 KAM CONSULTANTS PAGE 03/03
CITY_21MC100_0103952 13
NYC-WTC_000358168