KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 11-28-01
ADDRESS: 34[illegible] Chambers St., NY,NY 10282

T011128A

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES 0.5-5.0 (μ)	DETECTED >5.0 (μ)	Structure Density (struc/cm²)	Structure Concentration (struc/cc)
	Pier -25									
1	North Entr. of school - East	00:01	8:00	3	3	1437	0	0	<16.67	<0.00[illegible]
2	-11 — 11 - West	00:02	8:01	3	3	1437	0	0	<16.67	<0.00[illegible]

RECEIVED KAM CONSULTANTS 2001 NOV 28 AM 8:54

TECHNICIAN: R. Dymkowska

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX results to DDC	RECEIVED AT LAB BY: RL SAMPLE CONDITION UPON RECEIPT: Good DATE/TIME: 11-28-01

ANALYST: [signature] DATE RECEVED: 11/28 DATE OF ANALYS: 11/28

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

11/28/2001 13:00 7187293774 KAM CONSULTANTS PAGE 01/03