NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10-12-01
ADDRESS: 345 Chambers St., NY, NY 10282

T0110127

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER-25									
1	North Entrance of school - East	8:01	15:56	3	3	1425	0	0	<16.67	<0.0045
2	North Entrance of school - West	8:04	15:59	3	3	1425	0	0	<16.67	<0.0045

RECEIVED KAM CONSULTANTS 2001 OCT 12 PM 5:05

TECHNICIAN: Renata Dymkowska

ROTAMETER: KAM101

CHAIN OF CUSTODY	Pleas Analyze ASAP and FAX Results! DOE Hazmat (718) 291-1499 DDC OPERATIONS (212) 941-5356 DDC BOB ADAMS (607) 584-1134	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME: 10/12/01

ANALYST: DAVE CHEN DATE RECEVED: 10/12/01 DATE OF ANALYSIS 10/12/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

10/12/2001 18:12 7187293774 KAM CONSULTANTS PAGE 01/01
CITY_21MC100_010395392
NYC-WTC_000358317