NYC-WTC_000358331

NYC 9/11 Public Portal Document

10/17/2001 19:39 7187293774 KAM CONSULTANTS PAGE 01/02

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718)729-1997
Fax: (718)729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.
SAMPLING DATE: 10-17-01
ADDRESS: 345 Chambers St., NY, NY 10282

TO 11017H

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER-25									
1	North Entrance of H.S - East	7:59	15:58	3	3	1437	0	1	16.67	0.0045
2	" " - West	8:01	16:00	3	3	1437	0	0	< 16.67	< 0.0045

RECEIVED
KAM CONSULTANTS
2001 OCT 17 PM 5:11

TECHNICIAN: R. Dymkowski
ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX the results to DDC	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: [signature] DATE RECEVED: 10/17/01 DATE OF ANALYSIS: 10/17/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

CITY_21MC100_010395411