KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10-24-01
ADDRESS: 345 Chambers St., NY,NY 10282

T011025 A

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER-25									
1	North Entrance of H.S-East	8:01	15:58	3	3	1431	0	0	<16.67	<0.0045
2	North Entrance of H.S-West	8:03	16:00	3	3	1431	↓	↓	↓	↓

TECHNICIAN: R. Dymkowska

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX Results to DDC.	RECEIVED AT LAB BY: [signature] SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: ALEKE BARENGOW DATE RECEVED: 10/25/01 DATE OF ANALYSIS 10/25/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356