NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10/27/01
ADDRESS: 346 Chambers St., NY,NY 10282

T011028C

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER # 25									
1	OUTSIDE MAIN ENTRANCE - EAST SIDE OF SCHOOL	00.01	8:01	3	3	1440	0	0	416.67	<0.2045
2	↓ - WEST SIDE	00.02	8:03	3	3	1437	↓	↓	↓	↓

TECHNICIAN: A. MARTIROSSIAN / ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE ANALYSE ASAP AND FAX RESULTS DDC HAZMAT (718) 391-1499 DDC OPERATIONS (212) 941-5356 BOB ADAMS (609) 584-1134	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: ALEXIS KARAMBOY DATE RECEIVED: 10/29/01 DATE OF ANALYSIS

RECEIVED
KAM CONSULTANTS
2001 OCT 27 PM 5:27

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method
FAX RSULTS TO (212) 941-5356

CITY_21MC100_010395439

NYC-WTC_000358355