NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 10-27-01
ADDRESS: 345 Chambers St., NY, NY 10282

T01028A

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER-25									
1	North Entrance of H.S-East	8:02	16:01	3	3	1437	0	0	<16.67	<0.0049
2	— " — — — -West	8:04	16:03	3	3	1437	↓	↓	↓	↓

TECHNICIAN: R. Dymkowska
ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX Results to DDC.	RECEIVED AT LAB BY: 12 SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: ALEKS BAREWOOT DATE RECEVED: 10/28/01 DATE OF ANALYSIS 10/28/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

RECEIVED
KAM CONSULTANTS
2001 OCT 27 PM 5:27

10/28/2001 10:00 7187293774 KAM CONSULTANTS PAGE 03/03

CITY_21MC100_0103955519

NYC-WTC_000358409