NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

ANALYSIS REPORT

ASBESTOS IN AIR

Transmission Electron Microscopy

CLIENT: Department of Design and Construction - 30-30 Thomson Avenue, Long Island City, NY 11101
PROJECT ADDRESS: Stuyvesant H.S., 345 Chambers St., NY, NY 10282

Lab ID#	Client Sample ID#	Sample Location	Volume (liters)	Grid Openings Examined	Filter Area (mm^2)	Analytical Sensitivity (struct/cc air)	Asbestos Type(s)	Asbestos Structures (microns) 0.5-5.0	>5.0	Detected Total	Structure Density (struc/mm^2) Total	Structure Concentration (struc/cc) Total
T011201b-1	1	North Entrance of HS - East	1434	6	385	0.0045	ND	0	0	0	< 16.67	< 0.0045
T011201b-2	2	North Entrance of HS - West	1431	6	385	0.0045	ND	0	0	0	< 16.67	< 0.0045

Area Analyzed: 0.0600 mm^2
Grid Opening Area: 0.010 mm^2
Date Collected: 11/30/01(16:00-24:00)

Date Received: 12/1/01
Date Analyzed: 12/1/01
Date of Report: 12/3/01

Analyst: _____
Alex Barengolts

Lab Manager: _____
David Chen

Analysis performed according to AHERA Method (EPA 40 CFR Part 763 - Appendix A).Samples will be stored for ninety (90) days and then returned to the client upon request.
Sample volume is below recommended limit of the method

AIHA #: 100269 **NIST-NVLAP # : 102047** **NYS-DOH ELAP#: 11273**

CITY_21MC100_010404811

NYC-WTC_000358982