NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

# CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

**CLIENT:** NYC-DDC
**PROJECT:** Stuyvesant H.S.
**SAMPLING DATE:** 10-09-01
**ADDRESS:** 345 Chambers St., NY, NY 10282

T0110/0A

| FIELD DATA | | | | | | | LAB ANALYSIS | | | |
|---|---|---|---|---|---|---|---|---|---|---|
| SAMPLE # | LOCATION | TIME IN | TIME OUT | FLOW BEF. (lpm) | FLOW AFTER (lpm) | VOLUME (liters) | STRUCTURES DETECTED 0.5-5.0 (μ) | STRUCTURES DETECTED >5.0 (μ) | Structure Density (struc/mm²) | Structure Concentration (struc/cc) |
| 1 | Pier#25 - Across of North Exit of Stuyvesant H.S. | 20:52 | 23:55 | 7 | 7 | 1281 | 2 | 1 | 42.86 | 0.0128 |
| 2 | Pier#25 - East Side - BY Truck Unloading Area | 20:57 | 23:59 | 7 | 7 | 1274 | 0 | 0 | <14.29 | <0.0043 |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |
| | | | | | | | | | | |

TECHNICIAN: A. DIMITROPOULOS
ROTAMETER: KAM101

| | | |
|---|---|---|
| CHAIN OF CUSTODY | Plase analysq ASAP & fax results to<br>DDC-Hazmat (718) 391-1499<br>DDC-Operations (212) 941-5356<br>DDC-Bod Adams (609) 584-1134 | RECEIVED AT LAB BY:<br>SAMPLE CONDITION UPON RECEIPT:<br>DATE/TIME: 10/10/01 6:20 pm |

ANALYST: DATE RECEVED: 10/10/01 DATE OF ANALYSIS 10/11/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

CITY_21MC100_009251542

NYC-WTC_000358983