NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.
SAMPLING DATE: 10/15/01
ADDRESS: 345 Chambers St., NY,NY 10282

T011016R

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	PIEZ #25 NORTH OF EXIT STUYVESANT H.S.	24.01	0755	3	3	1422	0	0	<16.67	<0.004 J
2	PIEZ #25 NORTH WEST OF EX STUYVESANT H.S	2402	0757	3	3	1425	0	0	<16.67	<0.004 J

RECEIVED KAM CONSULTANTS OCT 16 PM 5:12

TECHNICIAN: DIMITRIOS M. SALIS, R. Dymkowska ROTAMETER: KAM101

CHAIN OF CUSTODY		
	FAX RESULTS TO D.D.C	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: DATE RECEVED: 10/16/01 DATE OF ANALYSIS 10/16/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

CITY_21MC100_009251571

NYC-WTC_000359013