NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.
SAMPLING DATE: 10-21-01
ADDRESS: 345 Chambers St., NY,NY 10282

TO110211

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	PIER # 2 S NORTH/EAST EXIT OF STUYVESANT H.S.	8 02	4 05	3	3	1449	0	0	<16.67	<0.00046
2	PIER # 2 S NORTH/EAST EXIT OF STUYVESANT H.S.	8 05	4 07	3	3	1446	0	0	<16.67	<0.00046

RECEIVED
KAM CONSULTANTS
2001 OCT 21 PM 5:58

TECHNICIAN: B. NOWAK
ROTAMETER: KAM101

CHAIN OF CUSTODY		RECEIVED AT LAB BY: KL SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: ALEKS BARENGOLTS DATE RECEIVED: 10/21/01 DATE OF ANALYSIS 10/21/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

CITY_21MC100_009251586

NYC-WTC_000359028