NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.
SAMPLING DATE: 11/3/01
ADDRESS: 345 Chambers St., NY, NY 10282

T011103Q

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION PIER # 25	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	OUTSIDE NORTH ENTRANCE OF SCHOOL - EAST SIDE	00.01	8:01	3	3	1440	0	0	46.67	<0.0046
2	↓ - WEST SIDE	00.01	8:03	3	3	1443	↓	↓	↓	↓

RECEIVED
KAM CONSULTANTS
2001 NOV -3 PM 5:48

TECHNICIAN: A. MARTIROSSIAN / R. DYMKOWSKA ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE, FAX RESULTS TO NYC DDC	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: ALEKS BARENBOIM DATE RECEVED: 11/3/01 DATE OF ANALYSIS 11/4/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

CITY_21MC100_009251623

NYC-WTC_000359062