NYC-WTC_000359072

KAM
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTOD FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 11-6-01
ADDRESS: 345 Chambers St., NY, NY 10282

T0/11060

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	North Entrance of school-East	8:02	16:00	3	3	1434	0	0	<16.67	<0.0045
2	-11 — 11 — -West	8:04	16:02	3	3	1434	0	0	<16.67	<0.0045

RECEIVED
KAM CONSULTANTS
2001 NOV -6 PM 3:25

TECHNICIAN: R. DYMKOWSKA

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX Results to DDC.	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: [signature] DATE RECEVED: 11/6/01 DATE OF ANALYSIS 11/7/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

CITY_21MC100_00925163

NYC 9/11 Public Portal Document