NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.
SAMPLING DATE: 11-13-01
ADDRESS: 345 Chambers St., NY, NY 10282

T011114A

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER-25						0.5-5.0 (μ)	>5.0 (μ)		
1	North Entrance of school - East	16:02	23.59	3	3	1431	0	0	<16.67	<0.0045
2	— 11 — 11 — West	16:03	00.00	3	3	1431	0	0	<16.67	<0.0045

TECHNICIAN: R. Dymkowska / A. MARTIROSSIAN ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX Results to DDC.	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST: DATE RECEVED: 11/14 DATE OF ANALYSIS 11/14

RECEIVED
KAM CONSULTANTS
2001 NOV 14 AM 7:42

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

CITY_21MC100_009251653

NYC-WTC_000359092