NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

RECEIVED
2001 DEC 15 AM 8:10

CHAIN OF CUSTOL FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 12/14/01
ADDRESS: 345 Chambers St., NY,NY 10282

TO112165

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER #25									
1	OUTSIDE NORTH ENTRANCE OF SCHOOL — EAST SIDE	16.01	23.57	3	3	1428	0	0	<16.67	<0.0045
2	↓ — WEST SIDE	16.04	23.58	3	3	1428	0	0	<16.67	<0.0045

TECHNICIAN: A. MARTIROSSIAN

ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE, FAX RESULTS TO NYC DDC	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST:

DATE RECEVED: 12/15

DATE OF ANALYSIS 12/15

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

CITY_21MC100_009251863

NYC-WTC_000359232