NYC 9/11 Public Portal Document

228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630

WARREN & PANZER ENGINEERS, P. C.

AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

8166

24 hr+/a | 12 hr+/a | (6 hr+/a) | 3 hr+/a | Immediate +/a

P.O. ____

W&P FILE #: 1079 01-02

CONTACT: -

CLIENT: Dep -

LABORATORY: ATC -

PROJECT: Building Cleanup

ANALYSIS METHOD: PCM 7400 | (TEM AHERA) | TEM EPA LEVEL II (circle one)

LOCATION: 116 NASSAU ST - 45 Add ST

TECHNICIAN: J Burgos

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START	FLOWRATE STOP	TIME ON	TIME OFF	TOTAL TIME	VOLUME (liters)	CONCENTR. (flb./cc.)
01	ROOF CENTRE - NORTH-WEST	5	-	3	3	7[00]	17[00]	600	1800	
02	ROOF CENTRE SOUTH SIDE - EAST SIDE	"	-	3	3	7[05]	17[05]	"	"	
03	CENTRE - EAST SIDE	"	-	3	3	7[07]	17[09]	"	"	
04	CENTRE EAST SIDE - NORTH -	"	-	3	3	7[09]	18[09]	"	"	
05	NORTH SIDE.	5	-	3	3	7[12]	18[12]	600	1800	
06	FIELD BLANK	1								
07	FIELD BLANK -	1								

COMMENTS:

SAMPLE BY: J W Burgos DATE: 06/19

SIGNATURE: J W Burgos

RELEASED BY: J W Burgos Laurie Beck DATE: 06/19

SIGNATURE: Laurie Beck 6/20/02

RECEIVED BY: ATC DATE: 6/20

SIGNATURE: 6/20/02

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

CITY_21MC100_000439167

NYC-WTC_000363602