NYC 9/11 Public Portal Document

6120 " HIKTEK

IENT: LIONS HEAD 110 DEVELOPMENT LLC

B LOCATION: 110-120 CHURCH ST

PRETESTING/POLYING/GLOVEBAGGING/GROSS REMOVAL/CLEANUP/FINAL AIR TESTING
PERIODIC AIR MONITORING/CEILING TILE REMOVAL/OTHER
(CIRCLE ONE)

EM&CA
Environmental Monitoring & Consulting Associates
P.O. BOX 872 · SOMERVILLE, NJ 08876 · (908) 249-3005 · FAX (908) 249-3384

HIKTEK

25/56 67211-67266

SAMPLE ID	LOCATION	DATE	L/MIN	PUMP NO	TIME ON	TIME OFF	TOTAL TIME	TOTAL VOLUME	FIBERS/ CC
01	16th floor DOOR NO 11 (1WA)	12/15/07	10		0730	0940	130	1300	
02	16th floor DOOR NO 9 (1WA)	12/15/07	10		0732	0942	130	1300	
03	16th floor DOOR NO 7 (1WA)	12/15/07	10		0734	0944	130	1300	
04	16th floor DOOR 6 (1WA)	12/15/07	10		0736	0946	130	1300	
05	16th floor DOOR 4 (1WA)	12/15/07	10		0738	0948	130	1300	
06	STAIR WAY EAST (OWA)	12/15/07	10		0740	0950	130	1300	

CODES: IWA = INSIDE WORK AREA ADJ = ADJACENT WORK AREA (CLEAN ROOM, CHANGE ROOM, SHOWER ROOM)
OUT = OUTSIDE WORK AREA OB = OUTSIDE BUILDING

FIELD NOTES: 24 Hrs Turn Around Results Jim Morrack MONITORING TECHNICIAN: DAVID EZEKWESILI
Call 6:917-295-0828 Moni NEMLIN

CITY_DEP_WORBY_CANNATA_SUBP_000021225

NYC-WTC_000366338

..6/20

IENT: Lion's Head 110 Development CCC

B LOCATION: 110-120 Church St

PRETESTING/POLYING/GLOVEBAGGING/GROSS REMOVAL/CLEANUP/FINAL AIR TESTING
PERIODIC AIR MONITORING/CEILING TILE REMOVAL/OTHER___
(CIRCLE ONE)

EM&CA
Environmental Monitoring & Consulting Associates
P O BOX 872 - SOMERVILLE NJ 08876 - (908) 249-3005 - FAX (908) 249 3384

SAMPLE ID	LOCATION	DATE	L/MIN	PUMP NO	TIME ON	TIME OFF	TOTAL TIME	TOTAL VOLUME	FIBERS/ CC
07	STAIR WAY 16th floor WEST (OWA)	12/15/01	10		0742	0952	130	1300	
08	STAIR WAY 16th floor CENTER	12/15/01			0744	0954	130	1300	
09	STAIR WAY 16th floor NORTH (OWA)	12/15/01			0746	0956	130	1300	
10	STAIR WAY 16th FLOOR ENTRANCE				0748	0958	130	1300	
11	15th floor DOOR NO 11 (IWA)				0815	1025	130	1300	
12	15th floor DOOR NO 9 (IWA)				0817	1027	130	1300	

CODES: IWA = INSIDE WORK AREA
OUT = OUTSIDE WORK AREA
ADJ = ADJACENT WORK AREA (CLEAN ROOM, CHANGE ROOM, SHOWER ROOM)
OB = OUTSIDE BUILDING

FIELD NOTES:_____ MONITORING TECHNICIAN: [signature]
Rani NEMLIN

NYC 9/11 Public Portal Document

IENT: Lion's Head 110 Development LLC

B LOCATION: 110-120 Church St

PRETESTING/POLYING/GLOVEBAGGING/GROSS REMOVAL/CLEANUP/FINAL AIR TESTING
PERIODIC AIR MONITORING/CEILING TILE REMOVAL/OTHER___
(CIRCLE ONE)

EMSA
Environmental Monitoring & Consulting Associates
P.O. BOX 872 · SOMERVILLE, NJ 08876 · (908) 249-3005 · FAX (908) 249-3384

SAMPLE ID	LOCATION	DATE	L/MIN	PUMP NO	TIME ON	TIME OFF	TOTAL TIME	TOTAL VOLUME	FIBERS/ CC
13	15th floor DOOR NO 7 (IWA)	12/15/04	10		0819	1029	130	1300	
14	15th floor DOOR NO 6 (IWA)				0821	1031	130	1300	
15	15th floor DOOR NO 4 (IWA)				0823	1033	130	1300	
16	15th floor EAST (OWA)				0825	1035	130	1300	
17	15th floor STAIRWAY WEST				0827	1037	130	1300	
18	15th floor STAIRWAY CENTER	↓	↓		0829	1039	130	1300	

CODES: IWA = INSIDE WORK AREA ADJ = ADJACENT WORK AREA (CLEAN ROOM, CHANGE ROOM, SHOWER ROOM)
OUT = OUTSIDE WORK AREA OB = OUTSIDE BUILDING

FIELD NOTES:_____ MONITORING TECHNICIAN: [signature]
Rami Nemlich

CITY_DEP_WORBY_CANNATA_SUBP_000021227

NYC-WTC_000366340

6/20

IENT: Lion's Head 110 Development LLC

B LOCATION: 110-120 Church St

PRETESTING/POLYING/GLOVEBAGGING/GROSS REMOVAL/CLEANUP/FINAL AIR TESTING
PERIODIC AIR MONITORING/CEILING TILE REMOVAL/OTHER___
(CIRCLE ONE)

EM&CA
Environmental Monitoring & Consulting Associates
P.O. BOX 872 • SOMERVILLE NJ 08876 • (908) 249-3005 • FAX (908) 249-3384

SAMPLE ID	LOCATION	DATE	L/MIN	PUMP NO	TIME ON	TIME OFF	TOTAL TIME	TOTAL VOLUME	FIBERS/ CC
19	15th floor STAIRWAY NORTH (OWA)	12/15/9	10		0831	1041	130	1300	
20	15th floor STAIRWAY ENTRANCE (OWA)				0833	1043	130	1300	
21	14th floor DOOR NO 11 (IWA)				1030	1240	130	1300	
22	14th floor DOOR NO 9 (IWA)				1032	1242	130	1300	
23	14th floor DOOR NO 7 (IWA)				1034	1244	130	1300	
24	14th floor DOOR NO 6 (IWA)				1036	1246	130	1300	

CODES: IWA = INSIDE WORK AREA
OUT = OUTSIDE WORK AREA
ADJ = ADJACENT WORK AREA (CLEAN ROOM, CHANGE ROOM, SHOWER ROOM)
OB = OUTSIDE BUILDING

FIELD NOTES:_____ MONITORING TECHNICIAN: [signature]
Rani NEMLIN

EM&CA
Environmental Monitoring & Consulting Associates
P.O. BOX 872 • SOMERVILLE NJ 08876 • (908) 249-3005 • FAX (908) 249-3364

IENT: Lions Head 110 Development

B LOCATION: 110 - 120 Church St

PRETESTING/POLYING/GLOVEBAGGING/GROSS REMOVAL/CLEANUP/FINAL AIR TESTING
PERIODIC AIR MONITORING/CEILING TILE REMOVAL/OTHER___
(CIRCLE ONE)

SAMPLE ID	LOCATION	DATE	L/MIN	PUMP NO	TIME ON	TIME OFF	TOTAL TIME	TOTAL VOLUME	FIBERS/ CC
25	14th floor DOOR No 4 (IWA)	[illegible]	10		1038	1248	130	1300	
26	14th floor STAIRWAY EAST				1040	1250	130	1300	
27	14th floor STAIRWAY WEST (OWA)				1042	1252	130	1300	
28	14th floor STAIRWAY CENTER (OWA)				1044	1254	130	1300	
29	14th floor STAIRWAY NORTH (OWA)				1046	1256	130	1300	
30	14th floor STAIRWAY ENTRANCE (OWA)				1048	1258	130	1300	

CODES: IWA = INSIDE WORK AREA
OUT = OUTSIDE WORK AREA
ADJ = ADJACENT WORK AREA (CLEAN ROOM, CHANGE ROOM, SHOWER ROOM)
OB = OUTSIDE BUILDING

FIELD NOTES:

MONITORING TECHNICIAN: [signature]
Rani NEMLIN

IENT: Lion's Head 110 Development

B LOCATION: 110-120 Church St

PRETESTING/POLYING/GLOVEBAGGING/GROSS REMOVAL/CLEANUP/FINAL AIR TESTING
PERIODIC AIR MONITORING/CEILING TILE REMOVAL/OTHER___
(CIRCLE ONE)

EMaCA
Environmental Monitoring & Consulting Associates
P.O. BOX 672 · SOMERVILLE NJ 08876 · (908) 249-3005 · FAX (908) 249-3384

SAMPLE ID	LOCATION	DATE	L/MIN	PUMP NO	TIME ON	TIME OFF	TOTAL TIME	TOTAL VOLUME	FIBERS/ CC
31	13th floor (IWA) NO11	12/15/07	00		1120	1330	130	1300	
32	NO9				1122	1332	130	1300	
33	NO7				1124	1334	130	1300	
34	NO6				1126	1336	130	1300	
35	NO-4				1128	1338	130	1300	
36	STAIRWAY OWA EAST				1130	1340	130	1300	

CODES: IWA = INSIDE WORK AREA
OUT = OUTSIDE WORK AREA
ADJ = ADJACENT WORK AREA (CLEAN ROOM, CHANGE ROOM, SHOWER ROOM)
OB = OUTSIDE BUILDING

FIELD NOTES:

MONITORING TECHNICIAN: [signature]

Rani NEMLIN

NYC 9/11 Public Portal Document

6126

IENT: Lion's Head 110 Development

B LOCATION: 110 - 120 Church St

EM&CA
Environmental Monitoring & Consulting Associates
P O BOX 872 - SOMERVILLE NJ 08876 - (908) 249-3005 - FAX (908) 249-3364

PRETESTING/POLYING/GLOVEBAGGING/GROSS REMOVAL/CLEANUP/FINAL AIR TESTING
PERIODIC AIR MONITORING/CEILING TILE REMOVAL/OTHER___
(CIRCLE ONE)

SAMPLE ID	LOCATION	DATE	L/MIN	PUMP NO	TIME ON	TIME OFF	TOTAL TIME	TOTAL VOLUME	FIBERS/ CC
37	STAIR WAY OWA WEST	12/15	LO		1132	1342	130	1300	
38	CENTER				1134	1344	130	1300	
39	NORTH				1136	1346	130	1300	
40	ENTRANCE				1138	1348	130	1300	
41	12th FLOOR (IWA) NO 11				1315	1525	130	1300	
42	NO 9				1317	1527	130	1300	

CODES: IWA = INSIDE WORK AREA ADJ = ADJACENT WORK AREA (CLEAN ROOM, CHANGE ROOM, SHOWER ROOM)
OUT = OUTSIDE WORK AREA OB = OUTSIDE BUILDING

FIELD NOTES:_____ MONITORING TECHNICIAN: Rani NEMLIN

CITY_DEP_WORBY_CANNATA_SUBP_000021231

NYC-WTC_000366344

NYC 9/11 Public Portal Document

6/20

IENT: Lion's Head 110" Development

B LOCATION: 110-120 Church St

PRETESTING/POLYING/GLOVEBAGGING/GROSS REMOVAL/CLEANUP/FINAL AIR TESTING
PERIODIC AIR MONITORING/CEILING TILE REMOVAL/OTHER___
(CIRCLE ONE)

EM&CA
Environmental Monitoring & Consulting Associates
P.O. BOX 832 · SOMERVILLE, NJ 08876 · (908) 249-3005 · FAX (908) 249-3384

SAMPLE ID	LOCATION		DATE	L/MIN	TIME ON	TIME OFF	TOTAL TIME	Volume TOTAL TIME	TOTAL VOLUME	FIBERS/ CC
43	12th NO7	floor IWA	12/15/01	10/1	1319	1529	130	1300		
44	NO6				1321	1531	130	1300		
45	NO4				1323	1533	130	1300		
46	~~12~~ th floor EAST	STAIR WAY OWA			1325	1535	130	1300		
47	WEST				1327	1537	130	1300		
48	CENTER				1329	1539	130	1300		

CODES: IWA = INSIDE WORK AREA
OUT = OUTSIDE WORK AREA
ADJ = ADJACENT WORK AREA (CLEAN ROOM, CHANGE ROOM, SHOWER ROOM)
OB = OUTSIDE BUILDING

FIELD NOTES:_____ MONITORING TECHNICIAN: Daniel Sze
Dani NEMLIN

CITY_DEP_WORBY_CANNATA_SUBP_000021232

NYC-WTC_000366345

NYC 9/11 Public Portal Document

CLIENT: Lion's Head 110 Development

JOB LOCATION: 110-120 Church St

PRETESTING/POLYING/GLOVEBAGGING/GROSS REMOVAL/CLEANUP/FINAL AIR TESTING
PERIODIC AIR MONITORING/CEILING TILE REMOVAL/OTHER___
(CIRCLE ONE)

EM&CA
Environmental Monitoring & Consulting Associates
P.O. BOX 872 - SOMERVILLE, NJ 08876 - (908) 249-3005 - FAX (908) 249-3364

SAMPLE ID	LOCATION	DATE	L/MIN	PUMP NO	TIME ON	TIME OFF	TOTAL TIME	TOTAL VOLUME	FIBERS/ CC
49	STAIRWAY OWA NORTH	12/15/01	10		1331	1541	130	1300	
50	ENTRANCE		10		1333	1543	130	1300	
51	field blank								
52									
53									
54									
55									
56									

CODES: IWA = INSIDE WORK AREA
OUT = OUTSIDE WORK AREA
ADJ = ADJACENT WORK AREA (CLEAN ROOM, CHANGE ROOM, SHOWER ROOM)
OB = OUTSIDE BUILDING

FIELD NOTES:_____ MONITORING TECHNICIAN: Daniel [illegible]
Rani NEMLIN

CITY_DEP_WORBY_CANNATA_SUBP_000021233

NYC-WTC_000366346