NYC 9/11 Public Portal Document

VATC ASSOCIATES INC

# AIR MONITORING DATA AND CHAIN OF CUSTODY FORM



**TURNAROUND TIME**
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

## ROJECT INFORMATION

| Client | 2 Project Name | 3 Project # | 4 Project Monitor | 4c Rotameter Number |
|---|---|---|---|---|
| Rethtech NYH | 2a Project Address 225 Rector | 3a Task # | 4a Air Sampler Chuck Simpson | CJ 001 |

| Date | 6. Abatement Location | 7. ☒ PCM (0 8 micron MCE) | 8 ☐ TEM (0 45 micron MCE) | 9 Type |
|---|---|---|---|---|
| 9-26-01 | Various Apt | Cassette/Filter Manufacture _____ Lot # _____ | Cassette/Filter Manufacture _____ Lot # _____ | a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other |

## AILY AIR SAMPLE RECORD

| 0. Sample I D Number | 11. Pump Number | 12. Sample Location 12a. IWA | 12b OWA | 12c Sample Coordinates | 13 Time (24 hrs clock) 13a Start | 13b End | 13c Total | 14 Flow Rate (L/min) 14a Start | 14b End | 14b Avg | 15 Total Air Vol (liters) | 16 # Fibers/Fields Minus Blank | 17 Fiber Conc F/CC |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 01 | | | | Field Blank | | | | | | | | 0/100 | |
| 02 | | | | Field Blank | | | | | | | | 0/100 | |
| 03 | | / | | Apt 21 D | 2030 | 2330 | 180 | 10 | 10 | 10 | 1800 | 1.5/100 | <0.003 |
| 04 | | / | | Apt 21 B | 2031 | 2331 | 180 | 10 | 10 | 10 | 1800 | 2/100 | <0.003 |
| 05 | | / | | Apt 20 C | 2033 | 2333 | 180 | 10 | 10 | 10 | 1800 | 1/100 | <0.003 |
| 06 | | / | | Apt 20 B | 2034 | 2334 | 180 | 10 | 10 | 10 | 1800 | 2/100 | <0.003 |
| 07 | | / | | Apt 19 G | 2036 | 2336 | 180 | 10 | 10 | 10 | 1800 | 3/100 | <0.003 |
| 08 | | / | | Apt 17 G | 2037 | 2337 | 180 | 10 | 10 | 10 | 1800 | 1/100 | <0.003 |

## HAIN OF CUSTODY

| 8 Relinquished By | 19 Received By | 20 Date | 21. Time |
|---|---|---|---|
| I | | 09/27/01 | 10:00 am |
| II | | | |

## LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

| 22 Lab Name | 23 Date | 24 Time |
|---|---|---|
| a Analyzed By A. Eckert | 09/27/01 | 16:00 |
| b QC By | | |
| c Lab Batch # 97150 | | |

25 Microscope Make/Serial # 1028
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

6 ATC Project Manager: T Burkhardt

27 Result To _____
Beeper/Phone #'s _____

28 Comments

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY 1 (1/01)

CITY_DEP_WORBY_CANNATA_SUBP_000002760

NYC-WTC_000366803

NYC 9/11 Public Portal Document

# AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 2

**TURNAROUND TIME**
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

## ROJECT INFORMATION

| Client: | 2 Project Name | 3 Project # | 4 Project Monitor | 4c Rotameter Number |
|---|---|---|---|---|
| Kenth Sqm | 2a. Project Address 225 Rector | 3a Task # | 4a Air Sampler Chuck Johnson | K 3001 |

| Date | 6 Abatement Location | 7 ☒ PCM (0 8 micron MCE) | 8 ☐ TEM (0 45 micron MCE) | 9 Type |
|---|---|---|---|---|
| 1-26 01 | Various Fl | Cassette/Filter Manufacture ____ Lot # ____ | Cassette/Filter Manufacture ____ Lot # ____ | a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other |

## AILY AIR SAMPLE RECORD

| 10 Sample I D Number | 11 Pump Number | 12 Sample Location 12a IWA | 12b OWA | 12c Sample Coordinates | 13 Time (24 hrs clock) 13a Start | 13b End | 13c. Total | 14 Flow Rate (L/min) 14a Start | 14b End | 14b Avg | 15 Total Air Vol (liters) | 16 # Fibers/Fields Minus Blank | 17 Fiber Conc F/CC |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Field Blank | | | | | | | | | |
| | | | | Field Blank | | | | | | | | | |
| 09 | | ✓ | | Capt 15 E | 2039 | 2339 | 180 | 0 | 0 | 0 | 1200 | 1.5/100 | <0.003 |
| 10 | | ✓ | | Capt 9 H | 2041 | 2341 | 180 | 0 | 0 | 0 | 1200 | 1/100 | <0.003 |
| 11 | | ✓ | | Capt 8 L | 2042 | 2342 | 180 | 0 | 0 | 0 | 1200 | 1/100 | <0.003 |
| 12 | | ✓ | | Capt 8 J. | 2043 | 2343 | 180 | 0 | 0 | 0 | 1200 | 1/100 | <0.003 |
| 13 | | ✓ | | Capt 7 H | 2045 | 2345 | 180 | 0 | 0 | 0 | 1200 | 2/100 | <0.003 |
| 14 | | ✓ | | Capt 5 E. | 2046 | 2346 | 180 | 0 | 0 | 0 | 1200 | 2/100 | <0.003 |

## CHAIN OF CUSTODY

| 18. Relinquished By | 19 Received By | 20 Date | 21 Time |
|---|---|---|---|
| I | | | |
| II | | | |

## LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

| 22 Lab Name | 23 Date | 24 Time |
|---|---|---|
| a Analyzed By | | |
| b QC By | | |
| c Lab Batch # 97150 | | |

25 Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26 ATC Project Manager

27 Result To ____
Beeper/Phone #'s ____

28 Comments

**WHITE** - File **YELLOW** - Client/Report **PINK** - Lab **GOLDENROD** - Field

NY-1 (1/01)

CITY_DEP_WORBY_CANNATA_SUBP_000002761

NYC-WTC_000366804

NYC 9/11 Public Portal Document

# AIR MONITORING DATA AND CHAIN OF CUSTODY FORM



**TURNAROUND TIME**
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

## ROJECT INFORMATION

| Client | 2 Project Name | 3 Project # | 4 Project Monitor | 4c Rotameter Number |
|---|---|---|---|---|
| RELATED MGM | 2a. Project Address 225 RECTOR | 3a Task # | 4a Air Sampler | C5001 |

| Date | 6. Abatement Location | 7. ☒ PCM (0 8 micron MCE) | 8 ☐ TEM (0 45 micron MCE) | 9. Type |
|---|---|---|---|---|
| 26 01 | VARIOUS APT | Cassette/Filter Manufacture / Lot # | Cassette/Filter Manufacture / Lot # | a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other |

## AILY AIR SAMPLE RECORD

| 10 Sample I D Number | 11 Pump Number | 12. Sample Location 12a. IWA | 12b OWA | 12c Sample Coordinates | 13 Time (24 hrs clock) 13a Start | 13b End | 13c Total | 14 Flow Rate (L/min) 14a Start | 14b End | 14b Avg | 15 Total Air Vol (liters) | 16 # Fibers/Fields Minus Blank | 17 Fiber Conc F/CC |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | Field Blank | | | | | | | | | |
| | | | | Field Blank | | | | | | | | | |
| 15 | | / | | APT 16A. | 2050 | 2350 | 180 | 10 | 10 | 10 | 1802 | 1/100 | <0.003 |
| 16 | | / | | APT 15H | 2400 | 300 | 180 | 10 | 10 | 10 | 1802 | 11/100 | 0.003 |
| 17 | | / | | APT 9J | 2401 | 301 | 180 | 10 | 10 | 10 | 1802 | 3/100 | <0.003 |
| 18 | | / | | APT 7K | 2402 | 302 | 180 | 10 | 10 | 10 | 1802 | 59/100 | 0.016 |
| 19 | | / | | APT 6K. | 2403 | 303 | 180 | 10 | 10 | 10 | 1802 | 6/100 | <0.003 |
| | | | | | | | | | | | | | |

## HAIN OF CUSTODY

| 18 Relinquished By | 19 Received By | 20 Date | 21 Time |
|---|---|---|---|
| | | | |
| I | KIC 2 | 09/27/01 | 10:00 AM |
| II | | | |

| 26. ATC Project Manager | 27 Result To / Beeper/Phone #'s |
|---|---|
| T BURKHARD | FAX to 212 245 3768 |

## LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

| 22 Lab Name | 23 Date | 24 Time |
|---|---|---|
| a Analyzed By A. Elbaz | 09.28.01 | 16:00 |
| b QC By | | |
| c Lab Batch # 97150 | | |

25 Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

28 Comments

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_DEP_WORBY_CANNATA_SUBP_000002762

NYC-WTC_000366805