NYC 9/11 Public Portal Document

SciLab Job #: **201092976**

Client Name: GCI Environmental Advisory, Inc.

Table I

Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (air)

N01-B4087; Rockrose Development Corp.; 333 Rector Place, NYC

SciLab Sample #	Client Sample #	Dilution Factor	Air Filtered (liters)	Area Analyzed (sq. mm.)	* Analytical Sensitivity (struc/cc air)	Asbestos Structures Detected (Microns) 0 5-5 0	>5.0	Total	Structure Density (struc/sq. mm.) >5.0	Total	Structure Concentration (struc/cc air) >5.0	Total	Type of Asbestos
01	33-9/24-33 Apt 14E Room Kitchen (CAS)		900	.09	0 0048	10 0	0 0	10.0	<11.1	111.1	<0 0048	0.0475	chrysotile

* concentration represented by the detection of 1 structure

** not analyzed

NSD No Asbestos Structures Detected

Reviewed By: _____; Analyzed By: _____ Glenn Massey Date: 9/25/01

NVLAP#: 200546-0

CITY_21MC100_002850425

NYC-WTC_000366997