NYC 9/11 Public Portal Document

SciLab Job #: **201103552**
Client Name: Parker House Services, Inc.

Table I
Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (air)
99 Battery Place, Apt. 18D

SciLab Sample #	Client Sample #	Dilution Factor	Air Filtered (liters)	Area Analyzed (sq. mm.)	* Analytical Sensitivity (struc/cc air)	Asbestos Structures Detected (Microns) 0.5-5.0	>5.0	Total	Structure Density (struc/sq. mm.) >5.0	Total	Structure Concentration (struc/cc air) >5.0	Total	Type of Asbestos
01	#008 Inside Apt. 18D		600	1	0.0064	0 0	0 0	0.0	<10	<10	<0.0064	<0 0064	NSD

concentration represented by the detection of 1 structure
not analyzed
SD- No Asbestos Structures Detected

Reviewed By: _____; Analyzed By: _____ Date: 10/26/01
Mark Peysakhov

VLAP#: 200546-0

11-22-2001 9:47AM FROM PARKER HOUSE SERVICE 9143374955 P.3

CITY_21MC100_002850450

NYC-WTC_000367017