NYC 9/11 Public Portal Document

SciLab Job #: **201092836**
Client Name: GCI Environmental Advisory, Inc.

Table I
Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (air)

N01-B4086; Rockrose Development Corp.; 22 River Terrace, New York, NY (Amended 9/29/01)

SciLab Sample #	Client Sample #	Dilution Factor	Air Filtered (liters)	Area Analyzed (sq. mm.)	* Analytical Sensitivity (struc/cc air)	Asbestos Structures Detected (Microns) 0.5-5.0	>5.0	Total	Structure Density (struc/sq. mm.) >5.0	Total	Structure Concentration (struc/cc air) >5.0	Total	Type of Asbestos
01	22- 9J- 9/22- 11 Apt. 9J, Room Kitchen / CAS		900	.09	0.0048	0.0	0.0	0.0	<11.1	<11.1	<0.0048	<0.0048	NSD

* concentration represented by the detection of 1 structure
** not analyzed
NSD No Asbestos Structures Detected

Reviewed By: _____; Analyzed By _____ Date: 9/24/2001
Mikhail Gruzman

NVLAP#: 200546-0

CITY_21MC100_002861813

NYC-WTC_000367178