NYC 9/11 Public Portal Document

Asbestos Air Sampling Data Form

Client: GREENWAY MANAGEMENT CORP Date: 12-28-01

Sampled By: A-BLAKE Rotometer #: 001 Project #:

Work Area: BUILDING 100 - 1ST FLOOR LOBBY AREA + 2ND FLR HALL-WAY + LAUNDRY 345 SOUTH

Sample # / Lab #	Sample Location	Code	Time Start	Time Stop	Total Minutes	Flow Rate Start	Flow Rate Stop	Total Volume	# Fibers /100 Fields	Results (f/cc)
1	INSIDE LAUNDRY ROOM 2ND FLOOR	4	11:00 AM	2:00 P.M	180	10	10	1800		
2	HALL-WAY 2ND FLOOR OUTSIDE LAUNDRYROOM	4	11:02 AM	2:02 P.M	180	10	10	1800		
3	HALL-WAY 1ST FLOOR LOBBY AREA BY ELEVATOR	4	11:05	2:05 P.M	180	10	10	1800		
4	INSIDE LAUNDRY ROOM 2ND FLOOR	4	2:07 P.M	5:07 P.M	180	10	10	1800		
5	HALL-WAY 2ND FLOOR OUTSIDE LAUNDRY ROOM	4	2:09 P.M	5:09 P.M	180	10	10	1800		
6	HALL-WAY 1ST FLOOR LOBBY AREA BY ELEVATOR	4	2:12 P.M	5:12 P.M	180	10	10	1800		
7	FIELD BLANK	1								
8	FIELD BLANK	1								

Codes: 1. Pre-Test, 2. Project, 3. Final, (4) Investigative, 5. Personal; A. Aggressive, D. Dormant; I. Inside Work Area, O. Outside Work Area; B. Excursion, T. TWA

Analysis: [X] TEM AHERA [ ] TEM Philadelphia [ ] PCM NIOSH 7400

Turnaround: [ ] ASAP [ ] 2 Day (48hr) [X] Same Day (12hr) [ ] _____

Relinquished: A-BLAKE Date/Time _____

Analyst: _____

Received: _____ Date/Time 12/28 5:0

Disposal By/Date 12/28 11:30

115 West 30th Street • 11th Floor • New York, New York 10001 • 212.279.1001 • 888.466.3620 • Fax 212.279.6747

Home Office: The Bellevue • Suite 600 • 200 S. Broad Street • Philadelphia, PA 19102 • 215.732.9499 • 888.789.8378 • Fax 215.732.9559

www.ALCEnvironmental.com

ALC ENVIRONMENTAL INCORPORATED

The First Choice for Environmental Testing & Consulting

CITY_DEP_WORBY_CANNATA_SUBP_000004116

NYC-WTC_000367306