ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

7871

Page 1 of 2

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RU

ECT INFORMATION 7871 15/18 91347-91364

YC-BCE	2. Project Name: PS234M 2a. Project Address: 242 Greenwich Str, NY, NY 10007	3. Project #: K1584-0823	4. Project Monitor: MARK NAKHUMOVICH 4a. Air Sampler: MARK Nakhumovich
4c. Rotameter Number: HP107			

5/25	6. ~~Assessment~~ Location: ENTIRE	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture ____ Lot # ____	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture MMI Lot # 0205916	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

AIR SAMPLE RECORD

Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc.
16				Field Blank									
17				Field Blank									
01				First Floor - hallway	6:35	10:35	240	8.0	8.0	8.0	1920		
02				Cafeteria	6:37	10:37	240	8.0	8.0	8.0	1920		
03				Gymnasium	6:39	10:40	241	8.0	8.0	8.0	1928		
04				Auditorium	6:41	10:42	241	8.0	8.0	8.0	1928		
05				North playground	6:43	10:43	240	8.0	8.0	8.0	1920		
06				West playground	6:45	10:46	241	8.0	8.0	8.0	1928		
07				Roof - South PART	6:47	10:49	242	8.0	8.0	8.0	1936		
08				First Floor - hallway	10:35	14:37	241	8.0	8.0	8.0	1928		
09				North playground	10:43	14:45	242	8.0	8.0	8.0	1936		
10				West playground	10:46	14:47	241	8.0	8.0	8.0	1928		
11				Roof - South PART	10:49	14:51	242	8.0	8.0	8.0	1936		
12				Classroom #Southside	6:49	10:51	242	8.0	8.0	8.0	1936		

N OF CUSTODY

Relinquished By:	19. Received By:	20. Date:	21. Time:
	M. Good	5.25.02	17:30

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: RRY	5.25.02	20:10
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079

Project Manager: Y. Efstathiou

27. Tested By: Y. Efstathiou

28. Comments:

Analysis Methodology:

VATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM 7871

Page 2 of 2

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RL

...ECT INFORMATION

...:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Numb
...YC-BCE	PS234M	K1584-0823	MARK NAKHUMOVICH	HP107
	2a. Project Address: 242 Greenwich St, NY, NY 10007		4e. Air Sampler: MARK Nakhumovich	

...:	6. ~~Monitoring~~ Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:		
5/25	ENTIRE	Cassette/Filter Manufacture ____ Lot # ____	Cassette/Filter Manufacture ____ Lot # ____	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA	f. ☐ Environmen g. ☒ Ambient h. ☐ Other

...Y AIR SAMPLE RECORD

...mple I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Con...
18				Field Blank									
				Field Blank									
13				Classroom #Southside	6:51	10:53	242	8.0	8.0	8.0	1936		
14				Classroom #Eastside	6:53	10:54	241	8.0	8.0	8.0	1928		
15				Kindergarden	6:55	10:57	242	8.0	8.0	8.0	1936		

...IN OF CUSTODY

...elinquished By:	19. Received By:	20. Date:	21. Time:
	M. Goof	5.25.02	17:30

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRey	5.25.02	20:10
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #: ☐ Nikon Labophot 23891 ☐ Nikon Labophot 23891 ☐ Nikon Labophot 23907

...Project Manager:	27. Reset To:	28. Comments:	Analysis Methodology:
Y. Efstathiou	Y. Efstathiou Beeper/Phone #'s (646) 772-1155		PCM - HIOSH 7400A