NYC-WTC_000375166

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other PU

ECT INFORMATION 7980 15/18 92998-92015

YC-BCE	2. Project Name: PS234M 2a. Project Address: 242 Greenwich St, NY, NY 10007	3. Project #: K1584-C823	4. Project Monitor: MARK NAKHUMOVICH 4a. Air Sampler: MARK Nakhumovich	4c. Rotameter Number: HP107
6/5	6. ~~Assessment~~ Location: ENTIRE	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture ____ Lot # ____	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture MMI Lot # 01205916	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

AIR SAMPLE RECORD

Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc.
16				Field Blank									
17				Field Blank									
01				First Floor - hallway	6:55	10:55	240	8.0	8.0	8.0	1920		
02				Cafeteria	6:57	10:57	240	8.0	8.0	8.0	1920		
03				Gymnasium	6:59	11:00	241	8.0	8.0	8.0	1928		
04				Auditorium	7:01	11:03	242	8.0	8.0	8.0	1936		
05				North playground	7:03	11:05	242	8.0	8.0	8.0	1936		
06				West playground	7:05	11:07	242	8.0	8.0	8.0	1936		
07				Roof - South PART	7:07	11:10	243	8.0	8.0	8.0	1944		
08				First Floor - hallway	10:55	14:55	240	8.0	8.0	8.0	1920		
09				North playground	11:05	15:05	240	8.0	8.0	8.0	1920		
10				West playground	11:07	15:08	241	8.0	8.0	8.0	1928		
11				Roof - South PART	11:10	15:11	241	8.0	8.0	8.0	1928		
12				Classroom #211	16:00	20:00	240	8.0	8.0	8.0	1920		

N OF CUSTODY

Relinquished By	19. Received By:	20. Date:	21. Time:
	[signature]	06/05/02	2130

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRuy	6.6.02	4:50
b. QC By:		
c. Lab Batch #: 7980		

25. Microscope Make/Serial #: ☐ Nikon Labophot 23891 ☐ Nikon Labophot 23891 ☐ Nikon Labophot 23907

Project Manager: Y. Efstathiou

27. Tested By: Y. Efstathiou

28. Comments:

Analysis Methodology:

CITY_21MC100_000463107

YAIL ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 2

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other KL

...ECT INFORMATION

...: NYC-BCE	2. Project Name: PS234M 2a. Project Address: 242 Greenwich St, NY, NY 10007	3. Project #: K1584-0823	4. Project Monitor: MARK NAKHUMOVICH 4a. Air Sampler: MARK Nakhumovich	4c. Rotameter Numb: HP107
6/5	6. ~~Assessment~~ Location: ENTIRE	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture ____ Lot # ____	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture ____ Lot # ____	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environme g. ☒ Ambient h. ☐ Other

...Y AIR SAMPLE RECORD

...mple I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Co...
18				Field Blank									
				Field Blank									
13				Classroom # 229	16:02	20:02	240	8.0	8.0	8.0	1920		
14				Classroom # 218	16:04	20:04	240	8.0	8.0	8.0	1920		
15				Kindergarden	16:08	20:08	240	8.0	8.0	8.0	1920		

...IN OF CUSTODY

...elinquished By:	19. Received By:	20. Date:	21. Time:
	DKog	06/05/02	21.30

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRM	6.6.02	4:50
b. QC By:		
c. Lab Batch #: 7980		

25. Microscope Make/Serial #: ☐ Nikon Labophot 238 ☐ Nikon Labophot 238 ☐ Nikon Labophot 239

...Project Manager: Y. Efstathiou

27. Sent To: Y. Efstathiou

Beeper/Phone #'s: (646) 772-1155

28. Comments:

Analysis Methodology: PCM - NIOSH 7400A