AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 2

ATC ASSOCIATES INC.

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other

ECT INFORMATION 8195 15/18 95525-95542

YC-BCE	2. Project Name: PS 234M 2a. Project Address: 242 Greenwich St, NY, NY 10007	3. Project #: K1584-C823	4. Project Monitor: M Nakhumovich 4a. Air Sampler:
4c. Rotameter No: HP107			

6/20	6. Location: ENTIRE	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture: Lot #:	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture: MMI Lot #: 01205916	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environ g. ☒ Ambient h. ☐ Other

AIR SAMPLE RECORD

Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber D
16				Field Blank									
17				Field Blank									
01				First Floor - hallway	7:06	11:06	240	8.0	8.0	8.0	1920		
02				Cafeteria	7:08	11:10	242	8.0	8.0	8.0	1936		
03				Gymnasium	7:10	11:13	243	8.0	8.0	8.0	1944		
04				Auditorium	7:12	11:14	242	8.0	8.0	8.0	1936		
05				North playground	7:14	11:16	242	8.0	8.0	8.0	1936		
06				West playground	7:16	11:18	242	8.0	8.0	8.0	1936		
07				Roof - South PART	7:18	11:20	242	8.0	8.0	8.0	1936		
08				First Floor - hallway	11:06	15:07	241	8.0	8.0	8.0	1928		
09				North playground	11:16	15:15	239	8.0	8.0	8.0	1912		
10				West playground	11:18	15:18	240	8.0	8.0	8.0	1920		
11				Roof - South PART	11:20	15:21	241	8.0	8.0	8.0	1928		
12				Classroom # 211	16:30	20:30	240	8.0	8.0	8.0	1920		

CUSTODY

Sample Name	19. Received By	20. Date	21. Time
	[signature]	6/20/2	21

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 11871)

22. Lab Name	23. Date	24. Time	25. Microscope Make Serial #
a. Analyzed By: [signature]	6/21	4:30	
b. QC By:			

Y Efstathiou

CITY_21MC100_002871003

ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 2

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

8195

...ECT INFORMATION

...: NYC-BOE	2. Project Name: PS234M 2a. Project Address: 242 Greenwich Str, NY, NY 10007	3. Project #: 14584-0823	4. Project Monitor: M. NAKHUMOVICH 4a. Air Sampler: M. NAKHUMOVICH	4c. Rotameter Number: HP107
...:	6. ~~Abatement~~ Location: ENTIRE	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture ____ Lot # ____	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture ____ Lot # ____	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

...Y AIR SAMPLE RECORD

...ple I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
18				Field Blank									
				Field Blank									
13				Classroom #225	16:32	20:32	240	8.0	8.0	8.0	1920		
14				Classroom #222	16:34	20:34	240	8.0	8.0	8.0	1920		
15				Kindergarden	16:40	20:40	240	8.0	8.0	8.0	1920		

...IN OF CUSTODY

...linquished By:	19. Received By:	20. Date:	21. Time:
	[illegible]	6/20/2	21

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By: [illegible]	6/20	6:30
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079

...C Project Manager: ANDREOU

27. Result To: Andreas C Andreou
Beeper/Phone #'s: (646) 772-1153

28. Comments:

Analysis Methodology: PCM - NIOSH 7400A

CITY_21MC100_002871004