NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other

PROJECT INFORMATION 8279 15/18 96544-96561

2. Project Name	3. Project #	4. Project Monitor	4c. Parameter No.
PS 234M	K1584-C823	M NAKHMANOVICH	4P107

2a. Project Address: 292 Greenwich St, NY, NY 10007

YC-23CE

6. Location	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
6-25 ENTIRE	Cassette/Filter Manufacturer: ____ Lot #: ____	Cassette/Filter Manufacturer: MMI Lot #: 01205916	a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environm g ☒ Ambient h ☐ Other

AIR SAMPLE RECORD

Sample ID number	11. Pump number	12. Sample Location: 12a. IN/A	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Blank	17. Fiber Co
16				Field Blank									
17				Field Blank									
01				First Floor - hallway	6:53	10:54	241	8.0	8.0	8.0	1928		
02				Cafeteria	6:55	10:56	241	8.0	8.0	8.0	1928		
03				Gymnasium	6:57	10:58	241	8.0	8.0	8.0	1928		
04				Auditorium	6:59	10:59	240	8.0	8.0	8.0	1920		
05				North playground	7:01	11:03	242	8.0	8.0	8.0	1936		
06				West playground	7:03	11:05	242	8.0	8.0	8.0	1936		
07				Roof - South part	7:05	11:07	242	8.0	8.0	8.0	1936		
08				First Floor - hallway	10:54	14:54	240	8.0	8.0	8.0	1920		
09				North playground	11:03	15:03	240	8.0	8.0	8.0	1920		
10				West playground	11:05	15:05	240	8.0	8.0	8.0	1920		
11				Roof - South part	11:07	15:07	240	8.0	8.0	8.0	1920		
12				Classroom #201	16:00	20:00	240	8.0	8.0	8.0	1920		

CHAIN OF CUSTODY

Sample #	19. Received By	20. Date	21. Time
	[illegible]	6/25/2	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name	23. Rec'vd By	23. Date	24. Time
EEA	[illegible]	6/26	2100

Yefstathiou

CITY_21MC100_002871104

NYC-WTC_000375263

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

ATC ASSOCIATES INC.

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

8279

CT INFORMATION

	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
IC-ASCE	PS234M	#4584-C823	M. NAKHUMOVICH	HP/07
	2a. Project Address: 242 Greenwich St, NY, NY 10007		4a. Air Sampler: M. NAKHUMOVICH	

5. Floor/Room Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:	
-25 ENTIRE	Cassette/Filter Manufacture:	Cassette/Filter Manufacture:	a. ☐ Background	c. ☐ Abatement
	Lot #:	Lot #:	b. ☐ Pre-Abate	d. ☐ Post-Abate
			e. ☐ OSHA	f. ☐ Environmental
				g. ☒ Ambient
				h. ☐ Other

AIR SAMPLE RECORD

Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
8				Field Blank									
				Field Blank									
3				Classroom # 225	16:02	20:02	240	8.0	8.0	8.0	1920		
4				Classroom # 222	16:04	20:04	240	8.0	8.0	8.0	1920		
5				Kindergarden	16:08	20:08	240	8.0	8.0	8.0	1920		

OF CUSTODY

Relinquished By:	19. Received By:	20. Date:	21. Time:
	[illegible]	8/25/12	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	8/26	2400
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Project Manager: ANDERSON

27. Result To: Andrea C Anderson
Beeper/Phone #'s: (646) 772-1152

28. Comments:

Analysis Methodology:
PCM - NIOSH 7400A
TEM - AHERA

CITY_21MC100_002871105

NYC-WTC_000375264