NYC-WTC_000377303

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION 6696 18/21 (M894) 73998-7498

1. Client:	2. Project Name / 2a. Project Address	3. Project #	4. Project Monitor:	4a. Air Sampler:	4c. Rotameter Number:
NYC-BOE	H.S. for Leadership & Public Services / 90 Trinity Place, NY, NY	14584-0864		A. EHOLODENICO	HP.53

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
2/15/02	as per protocol	Cassette/Filter Manufacture ____ Lot # ____	Cassette/Filter Manufacture ____ Lot # ____	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
-01,02				Field Blank open 30 sec									
-03				Field Blank sealed									
-04				Adj to main exit outside of Bldng.	07:40	11:26	226	8.0	8.0	8.0	1808		
-05				IN vestibule - 1st floor Northwest corner	07:42	11:29	227	8.0	8.0	8.0	1816		
-06				BSmt - adj to gym	07:47	11:35	228	8.0	8.0	8.0	1824		
-07				2nd Floor Adj to auditorium	07:55	11:43	228	8.0	8.0	8.0	1824		
-08				14th Floor - cafeteria By water fountain	08:01	11:48	227	8.0	8.0	8.0	1816		
-09				Main roof - adj to intake of HVAC	08:05	11:51	226	8.0	8.0	8.0	1808		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I		2/15/02	21:10
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	2/16	8:45
b. QC By:		
c. Lab Batch #: 6696		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: A. ANDREOU

27. Result To: Andreas C. Andreou
Beeper/Phone #'s (646) 772-1153

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/00)

CITY_21MC100_002872305

NYC-WTC_000377304

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

(M894)

1. Client:	2. Project Name / 2a. Project Address	3. Project #	4. Project Monitor: / 4a. Air Sampler:	4c. Rotameter Number:
NYC-BOE	H.S. for Leadership & Public Services / 90 Trinity Place, NY, NY	14584-0864	— / A. KHOLODENKO	HP-58

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture / Lot #	9. Type:
2/15/02	AS PER PROTOCOL	— / —	MMI / 98-224-617	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
— —				Field Blank / Field Blank									
-10				Out of Building By main entrance.	11:27	15:13	226	8.0	8.0	8.0	1808		
-11				North/west side of vestibule	11:30	15:17	227	8.0	8.0	8.0	1816		
-12				Main roof adj. to HVAC INTAKE	11:52	15:40	228	8.0	8.0	8.0	1824		
-13				13th Floor - hall adj. to elevator	15:45	19:32	227	8.0	8.0	8.0	1816		
-14				10th Floor - Room # 1015	15:50	19:36	226	8.0	8.0	8.0	1808		
-15				9th Floor - hallway adj. to Rm # 906	15:54	19:41	227	8.0	8.0	8.0	1816		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]	[signature]	2/15/02	21:10
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	2/16	8:45
b. QC By:		
c. Lab Batch #: 6696		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager:	27. Result To: / Beeper/Phone #'s	28. Comments:
A. ANDREOU	Andreas C. Andreou / (646) 772-1153	

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/00)

CITY_21MC100_002872306

NYC-WTC_000377305

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

1. Client:	2. Project Name (M894)	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC-BOE	H.S. for Leadership & Public Services	14584-0864	4a. Air Sampler: A. KHOLODENKO	MP53
	2a. Project Address 90 Trinity Place, NY, NY			

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:		
2/15/02	AS PER PROTOKOL	Cassette/Filter Manufacture ____ Lot # ____	Cassette/Filter Manufacture MMI Lot # 98-224-617	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA	f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
-16				8th Floor - Room # 805	15:59	19:45	226	8.0	8.0	8.0	1808		
-17				7th Floor - Hall By elevator bank	16:04	19:51	227	8.0	8.0	8.0	1816		
-18				6th Floor - Room # # 604	16:09	19:56	227	8.0	8.0	8.0	1816		
-19				5th Floor - Hall By Rm # 506	16:14	20:00	226	8.0	8.0	8.0	1808		
-20				4th Floor - Room # 404	16:19	20:06	227	8.0	8.0	8.0	1816		
-21				3rd Floor - Hall By elevators	16:22	20:09	227	8.0	8.0	8.0	1816		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I		2/15/02	21:10
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	2/16	8:45
b. QC By:		
c. Lab Batch #: 6696		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager:	27. Result To:	28. Comments:
A. ANDREOU	Andreas C. Andreou	
	Beeper/Phone #'s (646) 772-1153	

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/00)

CITY_21MC100_002872307