NYC 9/11 Public Portal Document

Table
Asbestos Microvac (ASTM 5575)
Carpe
New York City Law Department
100 Church Street
New York

* Sample ID : Lab Sample ID : Sample Date : * Sample Type : Floor: Surface Type: Location:	**Geometric Mean**	MV2004 4 8/9/2002 Microvac 20 Carpet Center of northern east/west corridor	MV2005 5 8/9/2002 Microvac 20 Carpet Lower eastern corridor	MV2006 6 8/13/2002 Microvac 20 Carpet North middle section, Room 8-1499	MV2007 7 8/13/2002 Microvac 20 Carpet South middle section, Espinal office	MV01 1 9/3/2002 Microvac 20 Carpet Southwest Office, Ilene Chin, 8-1445	MV02 2 9/3/2002 Microvac 20 Carpet Hallway outside Robert Weinberg office
CONSTITUENTS							
ASBESTOS (structures/cm^2)	685	2,140	3,210	**494,340**	535	1,070	<267

* Post Cleaning Target = <10,000 str/cm^2 (structures per square centimeter) individual sample and geometric mean of <1,000 str/cm^2

CITY_21MC100_011232921

TRC
Customer-Focused Solutions

NYC-WTC_000385455

NYC-WTC_000385456

NYC 9/11 Public Portal Document

Table
Asbestos Microvac (ASTM 5575)
Carpe
New York City Law Department
100 Church Street
New York

* Sample ID :	MV03	MV04	MV05	MV06	MV07	MV08	MV09
Lab Sample ID :	3	4	5	6	7	8	9
Sample Date :	9/3/2002	9/3/2002	9/3/2002	9/3/2002	9/3/2002	9/3/2002	9/3/2002
* Sample Type :	Microvac	Microvac	Microvac	Microvac	Microvac	Microvac	Microvac
Floor:	20	20	20	20	20	20	20
Surface Type:	Carpet	Carpet	Carpet	Carpet	Carpet	Carpet	Carpet
Location:	Hallway outside Sharon Reese's office	Inside Peter Sarw's office	Inside conference room	Inside cubicle, Mullen	Inside 8-1419 near window	Insdie 8-1405 Northwest	Northwest reception area
CONSTITUENTS							
ASBESTOS (structures/cm^2)	267	<356	535	<267	<267	<267	<267

* Post Cleaning Target = <10,000 str/cm^2 (structures per square centimeter) individual sample and geometric mean of <1,000 str/cm^2

CITY_21MC100_011232922

TRC
Customer-Focused Solutions

NYC-WTC_000385457

NYC 9/11 Public Portal Document

Table
Asbestos Microvac (ASTM 5575)
Carpe
New York City Law Department
100 Church Street
New York

* Sample ID :	MV10	MV11	MV12	MV13	MV14	MV15	MV16
Lab Sample ID :	10	11	12	13	14	15	16
Sample Date :	9/3/2002	9/3/2002	9/3/2002	9/3/2002	9/3/2002	9/3/2002	9/3/2002
* Sample Type :	Microvac	Microvac	Microvac	Microvac	Microvac	Microvac	Microvac
Floor:	20	20	20	20	20	20	20
Surface Type:	Carpet	Carpet	Carpet	Carpet	Carpet	Carpet	Carpet
Location:	Northwest inside 8-1410	Northwest outside room 8 2643	Main hallway outside 8-1438	North middle section room 8 1499	Hallway outside 1-0323 Northeast	Northeast hallway, outside 2-9506	Northeast hallway, outside 8-9770
CONSTITUENTS							
ASBESTOS (structures/cm^2)	<267	3,210	2,140	<267	<891	<891	2,675

* Post Cleaning Target = <10,000 str/cm^2 (structures per square centimeter) individual sample and geometric mean of <1,000 str/cm^2

CITY_21MC100_011232923

TRC
Customer-Focused Solutions

NYC-WTC_000385458

NYC 9/11 Public Portal Document

Table
Asbestos Microvac (ASTM 5575)
Carpe
New York City Law Department
100 Church Street
New York

* Sample ID :	MV17	MV18	MV19	MV20
Lab Sample ID :	17	18	19	20
Sample Date :	9/3/2002	9/3/2002	9/3/2002	9/3/2002
* Sample Type :	Microvac	Microvac	Microvac	Microvac
Floor:	20	20	20	20
Surface Type:	Carpet	Carpet	Carpet	Carpet
Location:	Southeast, room 8-1450	Hallway outside of room 8-1450	Southeast hallway outside 8-5959	Southeast hallway outside 8-9779
CONSTITUENTS				
ASBESTOS (structures/cm^2)	<535	1,070	1,070	2,140

* Post Cleaning Target = <10,000 str/cm^2 (structures per square centimeter) individual sample and geometric mean of <1,000 str/cm^2

TRC
Customer-Focused Solutions

CITY_21MC100_011232924