NYC-WTC_000385751

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 2

TURNAROUND TIME

[ ] 2 hrs [ ] 6 hrs [ ] 48 hrs [ ] Standard
[ ] 4 hrs [ ] 24 hrs [ ] 72 hrs [ ] Other

6303 15/50 69590 69639

PROJECT INFORMATION

1. Client	2. Project Name	3. Project #	4. Project Monitor	4c. Rotameter Number
AMEC/A	5 E. 59th St	21203-054	ZBKowalski / Tetra Tech	N/A
	2a. Project Address: 201 Warren St	3a. Task # 01	4a. Air Sampler: ZBKowalski / Tetra Tech	

5. Date:	6. Abatement Location:	7. [ ] PCM (0.8 micron MCE)	8. [X] TEM (0.45 micron MCE)	9. Type:	
1-10-02	6th FLOOR	Cassette/Filter Manufacture:	Cassette/Filter Manufacture:	a. [ ] Background	c. [ ] Abatement / f. [ ] Environmental
		Lot #:	Lot #: 12508	b. [ ] Pre-Abate	d. [ ] Post-Abate / g. [X] Ambient / e. [ ] OSHA / h. [ ] Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
01				Field Blank) PEN 30sec + close									
02				Field Blank) PEN 30sec + close									
03		X		6th Floor Corridor @ entrance to Equipment Room	15:35	19:05	210	9.0	9.0	9.0	1890		
04		X		6th FLOOR BOILER ROOM: LEFT SIDE ENTRANCE	15:36	19:06	210	9.0	9.0	9.0	1890		
05		X		6th FL. BOILER ROOM: BY WATER CHILLER	15:37	19:08	211	9.0	9.0	9.0	1899		
06		X		6th FLOOR MECH. ROOM: @ ENTRANCE	15:38	19:09	211	9.0	9.0	9.0	1899		
07		X		6th FLOOR MECH ROOM: BY LADDER TO 2nd LEVEL	15:39	19:11	212	9.0	9.0	9.0	1908		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I		1-10-02	
II		1/11/02	5:30pm
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRW	1/11/02	2:30
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
[ ] Nikon Labophot 238913
[ ] Nikon Labophot 238917
[ ] Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Ken Lasky

27. Result To: Ken Lasky
Beeper/Phone #'s 1800-759-7337 * 11852

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY 1 (1/01)

CITY_21MC100_011235164

NYC-WTC_000385752

NYC 9/11 Public Portal Document

VATC ASSOCIATES INC

6303

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number
NYCSCA	FCPM	2-120.02 x.P.7	SB Kowalski / T. Scarcella	#1
	2a. Project Address: 201 Varick ST.	3a. Task # 01	4a. Air Sampler: SB Kowalski / T. Scarcella	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture / Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture / Lot # 1358	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other
1-10-02	5th Floor			

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
08		X		Inside Room #501	1545	1911	209	9.0	9.0	9.0	1881		
09		X		Fw Corridor outside Room #506 & Elevator	1546	1915	209	9.0	9.0	9.0	1881		
10		X		Inside Room #510	1547	1917	209	9.0	9.0	9.0	1881		
11		X		Inside Exit #2	1550	1918	208	9.0	9.0	9.0	1872		
12		X		Fw Corridor by Room #526	1551	1920	209	9.0	9.0	9.0	1881		
12A		X		Inside Room #506	1552	1921	209	9.0	9.0	9.0	1881		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	[signature]		1/10/02	
II		TSD	1/10/02	5:20
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TSD	23. Date:	24. Time:
a. Analyzed By: RELEASED	1/10/02	8:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Dennis Hardy

27. Result To: Dennis Hardy
Reason/Phone #'s 1800 [illegible]

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_011235165

01/28/2002 10:45 FAX 212 353 8308 ATC 011

ATC ASSOCIATES INC.

6303

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 9

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client:	2. Project Name: PS 89M	3. Project #: 21203.089	4. Project Monitor: [illegible]	4c. Rotameter Number:
NYCSCA	2a. Project Address: 201 Warren St	3a. Task #: 01	4a. Air Sampler: [illegible]	[illegible]

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:		
1-10-02	Library 5th Fl.	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: ____ Lot #: 1358	a. ☐ Background	c. ☐ Abatement	f. ☐ Environmental
				b. ☐ Pre-Abate	d. ☐ Post-Abate	g. ☒ Ambient
					e. ☐ OSHA	h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
13		X		Inside Library North side	1555	1922	207	9.0	9.0	9.0	1863.		
14		X		Inside Library, Conference Room # 517	1556	1923	207	9.0	9.0	9.0	1863.		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]		1/10/02	
II	TD	1/11/02	5:30 pm
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: RKM	1/11/02	8:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: [signature]

27. Result To: [illegible]
Beeper/Phone #'s [signature]

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

NYC-WTC_000385754

NYC 9/11 Public Portal Document
01/29/2002 10:44 FAX 212 353 8308 ATC

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 4 of 7

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other ____

PROJECT INFORMATION

(6302)

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number
Plaza	PS 89 #1	2103-089	JB Kowalski / [illegible]	4P66
	2a. Project Address: 201 Warren ST.	3a. Task # 01	4a. Air Sampler: JB Kowalski / [illegible]	

5. Date:	6. Abatement Location:	7. ☐ PCM (plus micron MCE) Cassette/Filter Manufacture ____ Lot # ____	8. ☒ TEM (0.45 micron ACE) Cassette/Filter Manufacture ____ Lot # 1358	9. Type: a. ☐ Background b. ☐ Pre Abate c. ☐ Abatement d. ☐ Post Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other
1-10-02	4th Floor			

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
15		Y		Corridor Room #402	1600	1925	205	9.0	9.0	9.0	1845		
16		Y		Corridor by Room #404	1601	1926	205	9.0	9.0	9.0	1845		
17		Y		Corridor Room #406	1602	1927	205	9.0	9.0	9.0	1845		
18		Y		Corridor in Front of Room 426	1603	1928	205	9.0	9.0	9.0	1845		
19		Y		Corridor Room #428	1604	1929	205	9.0	9.0	9.0	1845		
20		Y		Corridor Stairwell #1	1604	1931	206	9.0	9.0	9.0	1854		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I. [signature]		1/10/02	
II.	JD	1/10/02	1730
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: RPeng	1-11-02	8:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: [signature]

27. Result To: Pam Hendy
Beeper/Phone #s/Fax #s 800-802-9012 pin # 1102

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_011235167

NYC-WTC_000385755

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC. 6303

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client	2. Project Name	3. Project #	4. Project Monitor	4c. Rotameter Number
NYC SCA	FS 6011	2205.639	K Townsend / P Sanchez	
	2a. Project Address: 201 WARREN ST. NY NY	3a. Task #	4a. Air Sampler: K Townsend, P Sanchez	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacturer / Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacturer / Lot #	9. Type: a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA	f. ☐ Environmental g. ☐ Ambient h. ☐ Other
1-10-02	3rd Floor		155B			

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. f/cc
				Field Blank									
				Field Blank									
21		W		Inside Room # 301	1610	1935	205	9.0	9.0	9.0	1845		
22		X		Inside STAIRWELL # 3	1611	1936	205	9.0	9.0	9.0	1845		
23		Y		Inside Room # 304	1613	1937	204	9.0	9.0	9.0	1836		
24		Z		Corridor adj to Room 304	1614	1938	204	9.0	9.0	9.0	1836		
25		AA		Inside Gym, North side	1616	1940	204	9.0	9.0	9.0	1836		
26		BB		Inside Gym South side	1617	1942	205	9.0	9.0	9.0	1845		
27		CC		Inside Room # 326	1617	1943	205	9.0	9.0	9.0	1845		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I		1/10/02	
I	TD	1/10/02	1700
II			

22. Lab Name: ATC – TEM	23. Date:	24. Time:
a. Analyzed By: RKing	1/10/02	8:00
b. QC By:		
c. Lab Batch #:		

LAB INFORMATION (ATC ELAP # 10979, ATC NVLAP # 1187)

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager:	27. Result To:	28. Comments:
P SANCHEZ	P. SANCHEZ	
	Beeper/Phone #'s	

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_011235168

ATC ASSOCIATES INC

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

6303

Page 6 of 9

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client	2. Project Name	3. Project #	4. Project Monitor	4c. Rotameter Number
NYC SCA	PS 89 M	21202 OF9	[illegible]	[illegible]
	2a. Project Address: 201 Warren St.	3a. Task #: 01	4a. Air Sampler: [illegible]	

5. Date	6. Abatement Location	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type	
1-10-02	3rd FL 200 R - 2nd FL 00 R	Cassette/Filter Manufacture: Lot #	Cassette/Filter Manufacture: Lot # 1353	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14h. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
28		Y		In Corridor Next To Room # 326 3rd FL	1619	1944	205	9.0	9.0	9.0	1595		
29		Y		Inside Room # 202 2nd FL	1626	1949	203	9.0	9.0	9.0	1527		
30		Y		Corridor Adj To Room # 202	1627	1950	203	9.0	9.0	9.0	1527		
31		Y		Inside Room # 204	1628	1952	204	9.0	9.0	9.0	1536		
32		Y		Inside General Offices	1629	1953	204	9.0	9.0	9.0	1536		
33		Y		Auditorium - Stage West	1630	1955	205	9.0	9.0	9.0	1595		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]		1-10-02	
II	[signature]	1-10-02	[illegible]
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: [illegible]	1/12	8:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: [signature]

27. Result To: [signature]
Beeper/Phone #'s 600 P074 177th HFS2

28. Comments:

WHITE - File YELLOW - Client/Report NK - Lab GOLDENROD - Field

NY-1 (1/01)

NYC-WTC_000385757

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

6203

Page 1 of

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client	2. Project Name	3. Project #	4. Project Monitor	4c. Rotameter Number
AMC SOIL	75 BROAD ST	21MC100 - 6203	C. Kamrani / L. Sanchez	100
	2a. Project Address: 101 WARREN ST. NY, NY	3a. Task #	4a. Air Sampler: C. Kamrani / L. Sanchez	

5. Date	6. Abatement Location	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
1-10-02	2nd FLOOR	Cassette/Filter Manufacture: ___ Lot #: ___	Cassette/Filter Manufacture: ___ Lot #: 185B	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IN/A	12b. OUT/A	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (l/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. f/CC
				Field Blank									
				Field Blank									
3 Y 05		Y		Auditorium - East side	1631	1917	206	9.0	9.0	9.0	1854		
3.5 Grimp		Y		STAIRWELL #2	1632	1919	207	9.0	9.0	9.0	1863		
3C 06		Y		CORRIDOR ADJ. TO ROOM 328	1633	2000	207	9.0	9.0	9.0	1863		
-04-													
Lab													

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]		1-10-02	
II	[signature]	1-10-02	5:20
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: RLG	1-11-02	8:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology:
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: L. SANCHEZ

27. Result To: L. SANCHEZ
Beeper/Phone #'s: ___

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_011235170

NYC-WTC_000385758

NYC 9/11 Public Portal Document

VATC ASSOCIATES INC

6303

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client:	2. Project Name:	3. Project #:	4. Project Monitor:	4c. Rotameter Number:
NYC DEP	FI 6910	11223-639	Lawrence Kamara	NP 100
	2a. Project Address: 201 WARREN ST NY NY	3a. Task #:	4a. Air Sampler: Lawrence Kamara	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.6 micron MCE) Cassette/Filter Manufacture: Lot #:	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture: Lot #: 13185	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other
1-10-02	1ST FLOOR			

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IN/A	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (l/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
37		IN		Kitchen	1635	2002	207	9.0	9.0	9.0	1863.		
38		IN		Kitchen - Storage Area	1636	2003	207	9.0	9.0	9.0	1863.		
39		IN		Cafeteria	1637	2005	208	9.0	9.0	9.0	1877.		
40		IN		Cafeteria	1638	2006	208	9.0	9.0	9.0	1872.		
41		IN		Stairwell #3	1639	2007	208 208	9.0	9.0	9.0	1872		
42		IN		Corridor 1st Fl by Stairwell #3	1640	2008	208	9.0	9.0	9.0	1877		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	[illegible]		1-10-02	
II		JEI	1/10/02	1730
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: RKing	1/10/02	5:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: E. SANCHEZ

27. Result To: E. SANCHEZ
Beeper/Phone #'s

28. Comments:

WHITE - File YELLOW - Client/Report INK - Lab GOLDENROD - Field NY-1 (1/01)

CITY_21MC100_011235171

NYC-WTC_000385759

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

6303

Page 2 of 2

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client	2. Project Name	3. Project #	4. Project Monitor	4c. Rotameter Number
NYC SCA	7 WTC BLDG III	1226.69	E. Fenwick / J. Spencer	HP 440
	2a. Project Address: 61 WARREN ST. NY NY	3a. Task #	4a. Air Sampler: E. Fenwick / J. Spencer	

5. Date	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:	
1-10-02	1ST FLOOR	Cassette/Filter Manufacturer:	Cassette/Filter Manufacturer:	a. ☐ Background	c. ☐ Abatement
		Lot #	Lot # 1550	b. ☐ Pre-Abate	d. ☐ Post-Abate
				e. ☐ OSHA	f. ☐ Environmental
					g. ☒ Ambient
					h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
43		X		Corridor 1st Flr By North exit	1641	2010	209	9.0	9.0	9.0	1881		
44		Y		Room # 128 (Inside)	1642	2011	209	9.0	9.0	9.0	1881		
45		N		Inside Room # 132	1644	2012	208	9.0	9.0	9.0	1872		
46		N		Inside Room # 134	1645	2013	208	9.0	9.0	9.0	1872		
47				OPEN 30sec + close									
48				OPEN 30sec + close									
49				Sealed Blanks									

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I		1-10-02	
II	FD	1/11/02	5:30
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1167)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: RRM	1-16-02	3:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 2389 13
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: F. SANCHEZ

27. Result To: F. SANCHEZ
Beeper/Phone #'s

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NV-1 (1/01)

CITY_21MC100_011235172