NYC 9/11 Public Portal Document

VATC ASSOCIATES INC.

DURING 7660 SCHOOL

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

Page I of III

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ASAP
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☑ Other

PROJECT INFORMATION

1. Client:	2. Project Name:	3. Project #:	4. Project Monitor:	4c. Rotameter Number:
NYC BOE	P.S. 89M	14584-0819	Daniel Finkley	HP125
	2a. Project Address: 101 WARREN ST.	3a. Task #	4a. Air Sampler:	

5. Date:	6. Abatement Location:	7. PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type:	
TUES 5/7/02	ALL FLOORS. PLAYGROUND/ROOF.	Cassette/Filter Manufacturer: Lot #:	Cassette/Filter Manufacturer: MULTI-METRICS Lot #:	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA
					f. ☐ Environmental g. ☑ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

AT BREATHING ZONE

AM

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. INSIDE/OUTSIDE	12b. INSIDE/OUTSIDE	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
07	[redacted]	[redacted]	[redacted]	Field Blank CLOSED.	[redacted]								
				Field Blank									
01		IN SIDE		Cafeteria	7:55	11:45	2:30	8.0	8.0	8.0	1840.		
02		↓		1st floor Hallway outside cafeteria	8:00	11:50	2:30	8.0	8.0	8.0	1840.		
03		↓	OUT SIDE	Playground - NORTH END	8:05	11:55	2:30	8.0	8.0	8.0	1840.		
04		↓	↓	Playground - SOUTH END.	8:10	12:00 PM	2:30	8.0	8.0	8.0	1840.		
05		IN SIDE		2ND floor - AUDITORIUM 217	8:15	12:05	2:30	8.0	8.0	8.0	1840.		
06		↓	↓	3rd floor - GYMNASIUM 315	8:20	12:10 PM	2:30	8.0	8.0	8.0	1840.		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I	[signature]	[signature]	5/7	8:[illegible]
II				
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	5/7	22:[illegible]
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager:	27. Result To:	28. Comments:
Yiannis Efstathiou	Y. Efstathiou	
	Beeper/Phone #'s 646-772-1155	

CITY_21MC100_00288711 4

NYC-WTC_000393294

DURING SCHOOL

7660

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

KUSH

Page II of III

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ASAP
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☑ Other

PROJECT INFORMATION

1. Client: NYC · BOE	2. Project Name: [illegible]	3. Project # 14584-0819	4. Project Monitor: Daniel Finkley
	2a. Project Address: 101 WARREN ST.	3a. Task #	4a. Air Sampler:
4c. Rotameter Number: HP125			
5. Date: TUES 5/7/02	6. Abatement Location: ALL FLOORS PLAYGROUND/ROOF.	7. [illegible] (0.8 micron MCE) Cassette/Filter Manufacturer: Lot #:	8. ☑ TEM (0.45 micron MCE) Cassette/Filter Manufacturer: MULTI-METRICS Lot #:

9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☑ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

AT BREATHING ZONE

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. AWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
018	[redacted]			Field Blank CLOSED.	[redacted]								
				Field Blank									
07		\	OUT SIDE	ROOF - CENTRAL	825	1215	230	8.0	8.0	8.0	1840		
08		IN SIDE		1st floor Hallway OUTSIDE OF Cafeteria	1151 AM	341	230	8.0	8.0	8.0	1840		
09		\	OUT SIDE	Play Ground - NORTH END.	1156 PM	346	230	8.0	8.0	8.0	1840		
010		\	↓	Play Ground - NORTH END.	1201 PM	351	230	8.0	8.0	8.0	1840		
011		\	↓	ROOF - CENTRAL.	1216 PM	406 PM	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]	[signature]	5/7	8 [illegible]
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC [illegible]	23. Date:	24. Time:
a. Analyzed By: [signature]	5/7	22:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Yiannis Efstahiou

27. Result To: Y. Efstahiou
Beeper/Phone #'s 646.772.1155

28. Comments:

CITY_21MC100_002887115

ATC ASSOCIATES INC.

AFTERSCHOOL 7660

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

KUSH

Page III of III

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☑ Other ASAP

PROJECT INFORMATION

1. Client: NYC·BOE	2. Project Name: PS 89M	3. Project # 14584-0819.	4. Project Monitor: Daniel Finkley	4c. Rotameter Number: HP125
	2a. Project Address: 201 WARREN ST.	3a. Task #	4a. Air Sampler:	
5. Date: TUES 5/7/02	6. Abatement Location: ALL FLOORS. PLAYGROUND/ROOF.	7. PCM (0.8 micron MCE) Cassette/Filter Manufacturer Lot #	8. ☑ TEM (0.45 micron MCE) Cassette/Filter Manufacturer MULTI-METRICS Lot #	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☑ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

AT BREATHING ZONE

P.M. - P.M.

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
019				Field Blank open.									
				Field Blank									
012		INSIDE		CLASS ROOM #202	256	606	190	9.5	9.5		1805		
013				CLASS ROOM #428	250	600	190	9.5	9.5		1805		
014				CLASS ROOM #3 BOYS LOCKER RM.	245	555	190	9.5	9.5		1805		
015				2ND floor Hallway SOUTHEND.	233	543	190	9.5	9.5		1805		
016.				4TH floor Hallway SOUTHEND.	240	550	190	9.5	9.5		1805		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]	[signature]	5/7	8pm
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC Tech	23. Date:	24. Time:
a. Analyzed By: [signature]	5/7	22:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Yiannis Efstahiou

27. Result To: Y. Efstahiou
Beeper/Phone #'s 646.772.1155

28. Comments:

CITY_21MC100_002887116