ATC ASSOCIATES INC

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 3

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other ASAP

PROJECT INFORMATION

7-8-8 16/19 88634-88652

1. Client:	2. Project Name:	3. Project #:	4. Project Monitor:	4c. Rotameter Number:
NYC- BOE	PS 89M 2a. Project Address: 201 WARREN ST NY NY	14584-0819	Kevin, Edgar 4a. Air Sampler: FitzPATRICK	SD087

5. Date:	6. Abatement Location:	7 ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type
5-9-02	ALL FLOORS PLAYGROUND/ROOF	Cassette/Filter Manufacture ____ Lot # ____	Cassette/Filter Manufacture MULTI METRICS Lot # 07100916	a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other ____

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14c. Avg	15. Total Air Vol. (liters)	16. # Fibers/ Fields Minus Blank	17. Fiber Conc. F/CC
01				Field Blank									
02				Field Blank									
03				CAFETERIA	7 47 AM	11:50	243	8.0	8.0	8.0	1944		
04				1ST FLOOR HALLWAY OUTSIDE OF CAFETERIA	7 49 AM	11:52	243	8.0	8.0	8.0	1944		
05				PLAYGROUND - NORTH	8 05 AM	12:07	242	8.0	8.0	8.0	1936		
06				PLAYGROUND - SOUTH	8 10 AM	12:11	241	8.0	8.0	8.0	1928		
07				2ND FLOOR AUDITORIUM Room 217	8 16 AM	12:20	244	8.0	8.0	8.0	1952		
08				3RD FLOOR GYM Room 315	8 19 AM	12:25	246	8.0	8.0	8.0	1968		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By	20. Date	21. Time
I. Kevin Fitzpatrick	[illegible]	05.09	9
II. C. Lamandrie			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date	24. Time
a. Analyzed By: [illegible]	5/10	3 [illegible]
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

26. ATC Project Manager: YIANNIS ETSTATHIOU

27. Results To: Y. Efstathiou
Beeper/Phone #'s ____

28. Comments: Rush

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

NYC-WTC_000394103

NYC 9/11 Public Portal Document

VATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other_____

TEST

PROJECT INFORMATION

1. Client:	2. Project Name: PS 89M	3. Project #: 14584 0819	4. Project Monitor: Kevin, Edgar	4c. Rotameter Number: SP-90
NYC - BOE	2a. Project Address: 201 WARREN ST NY/NY		4a. Air Sampler: FITZPATRICK	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type
5-9-02	ALL FLOORS PLAYGROUND/ROOF	Cassette/Filter Manufacture_____ Lot #_____	Cassette/Filter Manufacture MULTI METRICS Lot #_____	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other_____

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14c. Avg	15. Total Air Vol. (liters)	16. # Fibers/ Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
09				ROOF CRITICAL	8:23 AM	12:29	246	8.0	8.0	8.0	1968		
10				1ST FLOOR HALLWAY OUTSIDE OF CAFETERIA	11:52	15:54	242	8.0	8.0	8.0	1936		
11				PLAYGROUND NORTH	12:07	16:10	243	8.0	8.0	8.0	1944		
12				PLAYGROUND SOUTH	12:11	16:15	244	8.0	8.0	8.0	1952		
13				ROOF	12:29	16:30	241	8.0	8.0	8.0	1928		
14				CLASSROOM #425 NORTH VENT	16:00	20:02	242	8.0	8.0	8.0	1936		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By	20. Date	21. Time
I. [signature]	[signature]	05 09	9
II. [signature]			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: [illegible]	23. Date	24. Time
a. Analyzed By: [signature]	5/10	3 [illegible]
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM – NIOSH 7400A
TEM – AHERA

26. ATC Project Manager:	27. Results To: Y. Efstathiou	28. Comments:
YIANNIS ETSTATHIOU	Beeper/Phone #'s_____	

CITY_21MC100_0004897798

NYC-WTC_000394104

NYC 9/11 Public Portal Document

ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

7C: 8 S

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NIC- BCE	PS 89 M	14554-0519	E. Lemanovich	SD-90
	2a. Project Address 201 WARREN ST M/M	3a. Task #	4a. Air Sampler: E. Lemanovich	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
5-02	ALL FLOORS POLYCREW / ROOF	Cassette/Filter Manufacture _____ Lot # _____	Cassette/Filter Manufacture _____ Lot # _____	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
19				Field Blank Sealed Blank Field Blank									
15				CLASSROOM # EAST VENT GIRLS LOCKER ROOM	16:05	20:07	242	8.0	8.0	8.0	1936		
16				CLASSROOM # 302 SOUTH VENT	16:12	20:15	243	8.0	8.0	8.0	1944		
17				2ND FLOOR HALLWAY SOUTH END	16:20	20:23	243	8.0	8.0	8.0	1944		
18				3RD FLOOR HALLWAY SOUTH END	16:25	20:30	245	8.0	8.0	8.0	1960		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I E. Lemanovich	[illegible]	05.09	[illegible]
II			
III			

26. ATC Project Manager:	27. Result To:
YIANMS ETSTAHIOU	Y Efstathiou
	Beeper/Phone #'s _____

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	[illegible]	[illegible]
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

28. Comments:

WHITE - File **YELLOW** - Client/Report **PINK** - Lab **GOLDENROD** - Field

NY-1 (1/01)

CITY_21MC100_000489799