NYC 9/11 Public Portal Document

# AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of

TURNAROUND TIME: ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

## PROJECT INFORMATION

7408 7/10 84875-84884

| 1. Client: | 2. Project Name | 3. Project # | 4. Project Monitor: | 4c. Rotameter Number: |
|---|---|---|---|---|
| NYC-BOE | PS150M | 14584-C824 | Tim Amstislavskiy | SD-132 |
| | 2a. Project Address: 334 Greenwich Str, NY, NY 10013 | | 4a. Air Sampler: | |

| 5. Date: | 6. ~~Abatement~~ Location: | 7. ☐ PCM (0.8 micron MCE) | 8. ☒ TEM (0.45 micron MCE) | 9. Type: | |
|---|---|---|---|---|---|
| 04.14.02 | ENTIRE | Cassette/Filter Manufacture: ____ Lot #: ____ | Cassette/Filter Manufacture: MAT Lot #: 01206916 | a. ☐ Background b. ☐ Pre-Abate | c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other |

## DAILY AIR SAMPLE RECORD

| 10. Sample I.D. Number | 11. Pump Number | 12. Sample Location: 12a. IWA | 12b. OWA | 12c. Sample Coordinates | 13. Time (24 hrs clock): 13a. Start | 13b. End | 13c. Total | 14. Flow Rate (L/min.): 14a. Start | 14b. End | 14b. Avg | 15. Total Air Vol (liters) | 16. # Fibers/Fields Minus Blank | 17. Fiber Conc. F/CC |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| B-1, B-2 | | | | Field Blank | | | | | | | | | |
| B-3 | | | | Field Blank Sealed Blank | | | | | | | | | |
| 01 | | | | outside Building. | 620 | 1020 | 240 | 8 | 8 | 8 | 1920 | | |
| 02 | | | | Lobby | 625 | 1025 | 240 | 8 | 8 | 8 | 1920 | | |
| 03 | | | | outside Building | 1020 | 1420 | 240 | 8 | 8 | 8 | 1920 | | |
| 04 | | | | Lobby | 1025 | 1425 | 240 | 8 | 8 | 8 | 1920 | | |
| 05 | | | | multipurpose room | 1030 | 1429 | 239 | 8 | 8 | 8 | 1912 | | |
| 06 | | | | Counseling office | 1034 | 1434 | 240 | 8 | 8 | 8 | 1920 | | |
| 07 | | | | Nurse's office | 1038 | 1439 | 241 | 8 | 8 | 8 | 1928 | | |

## CHAIN OF CUSTODY

| 18. Relinquished By | 19. Received By | 20. Date: | 21. Time: |
|---|---|---|---|
| I | [illegible] | 04.14.2 | 5PM |
| II | | | |
| III | | | |

## LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

| 22. Lab Name: [illegible] | 23. Date: | 24. Time: |
|---|---|---|
| a. Analyzed By: [illegible] | 4/15 | 18:00 |
| b. QC By: | | |
| c. Lab Batch #: | | |

25. Microscope Make/Serial #:
- ☐ Nikon Labophot 238913
- ☐ Nikon Labophot 238917
- ☐ Nikon Labophot 239079

Analysis Methodology:
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Y. Efstathiou

27. Result To: Yiannis Efstathiou
Beeper/Phone #'s: (646) 772-1155

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

CITY_21MC100_0029197770

NYC-WTC_000397019