ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page _____ of _____

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other ASAP

PROJECT INFORMATION

7366 17/20 84208-8472 714 584865

1. Client:	2. Project Name:	3. Project #:	4. Project Monitor:	4c. Rotameter Number:
NYC. BOE.	HS. ECONOMICS & FINANCE	~~[illegible]~~	D. Giraldo	HP 88
	2a. Project Address: 100 Trinity Place.	3a. Task #:	4a. Air Sampler:	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:	
4-9-02	ENTIRE.	Cassette/Filter Manufacture: ____ Lot #: ____	Cassette/Filter Manufacture: NVC Lot #: 98307617	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA ☒ Environmental g. ☐ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
01				Field Blank Field									
02				Field Blank									
03			x	Roof South West	0730	11:00	210	8.0	8.0	8.0	1680		
04				8th Floor Cafeteria	0732	11:02	210	8.0	8.0	8.0	1680		
05			x	7th FL. Staircase B, at open	0734	11:04	210	8.0	8.0	8.0	1680		
06				1th FL - Auditorium left side. Entrance	0736	11:06	210	8.0	8.0	8.0	1680		
07			x	1th FL Lobby Next to RM #102	0738	11:09	211	8.0	8.0	8.0	1688		
08			x	outside the bldg Right side Main Entrance	0742	11:14	212	8.0	8.0	8.0	1696		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I D. Giraldo	MI	4.9.2	10
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By: [illegible]	4/10	4:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Mark Ferguson

27. Result To: Yoanis. EF.
Beeper/Phone #'s 646) 7721155

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page _____ of _____

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other ASAP

7366

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
N.Y.C. BOE.	H.S. of Economics	14584865	D. [illegible]	HP 88
	2a. Project Address: 100 Trinity Pl.	3a. Task #	4a. Air Sampler:	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
4-9/02	Entire	Cassette/Filter Manufacture ____ Lot # ____	Cassette/Filter Manufacture ____ Lot # ____	a. ☐ Background b. ☐ Pre-Abate c. ☒ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☒ Environmental g. ☐ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
09				Roof South West	1140	1514	214	8.0	8.0	8.0	1712		
10				Staircase B - 7th floor open staircase	1142	1517	215	8.0	8.0	8.0	1720		
11				1th floor - Lobby Next to RM 102A	11:43	1518	215	8.0	8.0	8.0	1720		
12				Main Entrance Right Side.	11:45	1521	216	8.0	8.0	8.0	1728		
13				9th Fl. hallway	1601	1937	216	8.0	8.0	8.0	1728		
14				8th Fl Room Adj Elevater.	1603	1939	216	8.0	8.0	8.0	1728		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I D. [illegible]	[illegible]	4.9.2	10
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: [illegible]	23. Date:	24. Time:
a. Analyzed By: [illegible]	4/10	4:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Mark [illegible]

27. Result To: Vianni S. Ef.
Beeper/Phone #'s 646) 772-1155.

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

NYC-WTC_000404877

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

ATC ASSOCIATES INC.

Page _____ of _____

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other ASAP

ROJECT INFORMATION 7366

1. Client:	2. Project Name / 2a. Project Address	3. Project # / 3a. Task #	4. Project Monitor / 4a. Air Sampler:	4c. Rotameter Number:
NYC-BOE	H.S. Economics / 100 Trinity	14584865	D. Lundo	HP 88

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type:	
4-9-02	Entire	Cassette/Filter Manufacture _____ Lot # _____	Cassette/Filter Manufacture _____ Lot # _____	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☑ Environmental g. ☐ Ambient h. ☐ Other

AILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
15				7th Fl Corridor	1605	1941	216	8.0	8.0	8.0	1728		
16				6th Fl. Adj RM-602-604	1607	1943	216	8.0	8.0	8.0	1728		
17				5th Fl Corridor Adj 303-304.	1609	1945	216	8.0	8.0	8.0	1728		
18				4th Fl Bet 303-304 and Corridor	1610	1947	217	8.0	8.0	8.0	1736		
19				3rd Adj Custodian RM 105.	1612	1949	217	8.0	8.0	8.0	1736		
20				Sealed				8.0					

HAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I			4.9.2	10
II				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:	4/10	6:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
- ☐ Nikon Labophot 238913
- ☐ Nikon Labophot 238917
- ☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

6. ATC Project Manager: Lori K Duggan

27. Result To: Y Davis
Beeper/Phone #'s 646) 772-1155

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_00290081