NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 5/4/02
ADDRESS: 345 Chambers St., NY, NY 10282

T020505B

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	Roof #25 NORTH EXIT OF STUYVESANT H.S.	07:00	17:00	3	3	1800	0	0	<20.0	<0.0043
2	↓ North west site	07:01	17:01	3	3	1800	0	0	<20.0	<0.0043

TECHNICIAN: D. SALLS
ROTAMETER: KAM101

CHAIN OF CUSTODY	
	FAX Results TO N.Y.C D.D.C

RECEIVED AT LAB BY:
SAMPLE CONDITION UPON RECEIPT:
DATE/TIME:

ANALYST: ALEKS BARENBERG DATE RECEVED: 5-5-02 DATE OF ANALYSIS 5-7-02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

RECEIVED
KAM CONSULTANTS
2002 MAY -5 PM 12:44

SUBJECT TO PROTECTIVE ORDER NO. 3, JULY 2009
CONFIDENTIAL,
CITY_21MC100_011816086

NYC-WTC_000408317