NYC 9/11 Public Portal Document

Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 5-19-02
ADDRESS: 345 Chambers St., NY, NY 10282

TO20520T

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER 25									
1	North Entrance of school-East	7:00	17:00	3	3	1800	0	0	< 20.0	< 0.0043
2	-11- — -11- — West	7:02	17:02	3	3	1800	0	0	< 20.0	< 0.0043

RECEIVED
KAM CONSULTANTS
2002 MAY 20 P 7:17

TECHNICIAN: Renata Dymkowska ROTAMETER KAM101

CHAIN OF CUSTODY		
	FAX results to DDC.	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: Good DATE/TIME:

ANALYST: ALEKS BAKENOWSKI DATE RECEVED: 5-20-02 DATE OF ANALYSIS 5-20-02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method
FAX RSULTS TO (212) 941-5356

SUBJECT TO PROTECTIVE ORDER NO.3, JULY 2009 CONFIDENTIAL,
CITY_21MC100_011816101

NYC-WTC_000408331