NYC 9/11 Public Portal Document

GPS Environmental Consultants, Inc.
31 Trescott Path
Fort Salonga, NY 11768
Tel: 631 269 4205 Fax: 631 269 9527

Form 1 of 2

020419A

Chain of Custody Record

Client: 105 Broad St **Page** 1 of 1

Project Location: Bldg Facade **Date Sampled:** 4-19-02

Address: 105 Broad st **Comments:**
MANHATTAN

Sampled by_____

Type of Sample = W P=Pre-Abatement D=During Abatement POST=Post Abatement A= Ambient
Analysis Type = PLM PCM=Phase Contrast Microscopy TEM=Transmission Electron Microscopy
Lead Air=NIOSH 7082 PLM = Polarized Light Microscopy W=Wipe Sample

NO.	Sample ID	Sample Location	Sample Type Air	Sample Type Bulk	Total Volume (liters)	Analysis Type
1		window Broad st. side				
2		"				
3		"				
4		window water st side				
5		"				
6		Bldg Facade Broad st side				
7		"	→ ANALYSIS REQUESTED FOR			
8		"	HEAVY METALS			
9		Bldg Facade water st. side				
10		"				
11		105 Broad st ent. door				
12		water st. ent door				

Relinquished By	Date	Time	Shipped By	Received by:	Date	Time
A Palermo	4-19	1130A	A Palermo	AL	4/19/02	11:17

DOA · 4/22
JL

CONFIDENTIAL, CITY_21MC100_003387186
SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

NYC-WTC_000409072