NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: GPS Environmental Consultants, Inc., 31 Trescott Path, Fort Salonga, New York, 11768
BUILDING ADDRESS: 105 Broad Street, Manhattan, New York - Building Façade
PROJECT#:

Client Sample ID# :	1	2	3	4	5
Lab Sample ID# :	020419A-1644	020419A-1645	020419A-1646	020419A-1647	020419A-1648
Sample Location:	Window Broad Street Side	Window Broad Street Side	Window Broad Street Side	Window Water Street Side	Window Water Street Side
Homogeneity:	Yes	Yes	Yes	Yes	Yes
Sample Description:	Wipe	Wipe	Wipe	Wipe	Wipe
Color:	Wh/Blk	Wh/Blk	Blk	Blk	Wh/Brn
Texture:	Mixed	Mixed	Mixed	Mixed	Mixed
Sample Treatment:	None	None	None	None	None
Asbestos Present: (Type & Percent)	ND	ND	ND	ND	ND
Total Percent Asbestos:	**0%**	**0%**	**0%**	**0%**	**0%**
Other Fibr. Mat. (Type & Percent):	<1%CELL 3%SYNTH	<1%CELL 5%SYNTH	3%CELL 2%SYNTH	5%CELL 2%SYNTH	3%CELL 5%SYNTH
Non Fibr. Mat. (Percent):	96%	94%	95%	93%	92%

Date Received: 4/19/02
Date of Analysis: 4/22/02
Date of Report: 4/22/02

Analyst: Roody Louis **Lab Manager:** David Chen

* Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
* Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
* PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
* Samples will be stored for ninety (90) days and then returned to the client upon request
* The results relate only to the items calibrated or tested.
* The certificate of report shall not be reproduced without the written approval of the laboratory.
* The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273 *NIST-NVLAP # 102047* *AIHA #: 100269*

CONFIDENTIAL, CITY_21MC100_003387187
SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

NYC-WTC_000409073

NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: GPS Environmental Consultants, Inc., 31 Trescott Path, Fort Salonga, New York, 11768
BUILDING ADDRESS: 105 Broad Street, Manhattan, New York - Building Façade
PROJECT#:

Client Sample ID# :	6	8	9	10	11
Lab Sample ID# :	020419A-1649	020419A-1650	020419A-1651	020419A-1652	020419A-1653
Sample Location:	Bldg. Façade Broad Street Side	Bldg. Façade Broad Street Side	Bldg. Façade Water Street Side	Bldg Façade Water Street Side	105 Broad Street Ent. Door
Homogeneity:	Yes	Yes	Yes	Yes	Yes
Sample Description:	Wipe	Wipe	Wipe	Wipe	Wipe
Color:	Wh	Wh/Br	Wh/Blk	Wh	Wh
Texture:	Mixed	Mixed	Mixed	Mixed	Mixed
Sample Treatment:	None	None	None	None	None
Asbestos Present: (Type & Percent)	ND	ND	ND	ND	ND
Total Percent Asbestos:	**0%**	**0%**	**0%**	**0%**	**0%**
Other Fibr. Mat. (Type & Percent):	30%SYNTH	5%SYNTH	<1%FBGL <1%CELL	3%SYNTH	5%SYNTH
Non Fibr. Mat. (Percent):	70%	95%	98%	97%	95%
Date Received:	4/19/02				
Date of Analysis:	4/22/02				
Date of Report:	4/22/02				

Analyst: R. Louis — Roody Louis **Lab Manager:** D.C. — David Chen

* Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
* Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
* PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
* Samples will be stored for ninety (90) days and then returned to the client upon request
* The results relate only to the items calibrated or tested.
* The certificate of report shall not be reproduced without the written approval of the laboratory.
* The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273 ***NIST-NVLAP # 102047*** ***AIHA #: 100269***

CONFIDENTIAL, CITY_21MC100_003387188
SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

NYC-WTC_000409074

NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: GPS Environmental Consultants, Inc., 31 Trescott Path, Fort Salonga, New York, 11768
BUILDING ADDRESS: 105 Broad Street, Manhattan, New York - Building Façade
PROJECT#:

Client Sample ID# :	12
Lab Sample ID# :	020419A-1654
Sample Location:	Water Street Entrance Door
Homogeneity:	Yes
Sample Description:	Wipe
Color:	Wh
Texture:	Mixed
Sample Treatment:	None
Asbestos Present: (Type & Percent)	ND
Total Percent Asbestos:	**0%**
Other Fibr. Mat. (Type & Percent):	<1%FBGL 5%SYNTH
Non Fibr. Mat. (Percent):	94%
Date Received:	4/19/02
Date of Analysis:	4/22/02
Date of Report:	4/22/02

Analyst: Roody Louis **Lab Manager:** David Chen

* Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
* Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
* PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
* Samples will be stored for ninety (90) days and then returned to the client upon request
* The results relate only to the items calibrated or tested.
* The certificate of report shall not be reproduced without the written approval of the laboratory.
* The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273 *NIST-NVLAP # 102047* *AIHA #: 100269*

CONFIDENTIAL, CITY_21MC100_003387189

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

NYC-WTC_000409075