ATC ASSOCIATES INC.

6668

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

7/10 73608-73617

Page _____ of _____

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client:	2. Project Name: AMBIENT AIR SAMPLING	3. Project #: 11534-865	4. Project Monitor: [illegible]	4c. Rotameter Number:
NYCROE	2a. Project Address: 100 TRINITY PL NY NY		4a. Air Sampler: [illegible]	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type:
2-13-02	8th Floor	Cassette/Filter Manufacture _____ Lot # _____	Cassette/Filter Manufacture MMI Lot # 00263916	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
[illegible]				Field Blank									
[illegible]				Field Blank									
[illegible]				open blank									
[illegible]				next to stairwell 2 8th floor.	8 15 AM	11 [illegible] AM	190	9.5	9.5	[illegible]	[illegible]		
[illegible]				next to passenger elevator car #1 8th fl	8 17 AM	11 21 AM	190	9.5	9.5	[illegible]	[illegible]		
[illegible]				[illegible] 8th fl kitchen	8 19 AM	11 [illegible] AM	191	9.5	[illegible]	[illegible]	[illegible]		
[illegible]				northside of 8th fl kitchen.	8 21 AM	11 33 AM	192	9.5	[illegible]	[illegible]			
[illegible]				[illegible] ceiling 8th fl elevator bank.	8 23 AM	11 34 AM	194	9.5	[illegible]	[illegible]	[illegible]		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [illegible]	JD	2/13/02	16:15
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRMy	2/13/02	17:20
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: [illegible]

27. Result To: _____
Beeper/Phone #'s _____

28. Comments:

WHITE - File **YELLOW** - Client/Report **PINK** - Lab **GOLDENROD** - Field

NY-1 (1/00)

CITY_21MC100_010190691

ATC ASSOCIATES INC.

6668

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page ____ of ____

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other ____

PROJECT INFORMATION

1. Client:	2. Project Name: AMBIENT AIR SAMPLING	3. Project #: 14554.565	4. Project Monitor: [illegible]	4c. Rotameter Number: [illegible]
NYCDOE	2a. Project Address: 100 TRINITY PL NYNY		4a. Air Sampler: [illegible]	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☑ TEM (0.45 micron MCE)	9. Type:
2-13-02	8TH FLOOR	Cassette/Filter Manufacture ____ Lot # ____	Cassette/Filter Manufacture ____ Lot # ____	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☑ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
09				CONTROL OF SODA MACHINE IN CAFETERIA CEILING	8:25 AM	11:41 AM	146	9.5	9.5	7.5	1062		
10				[illegible] OF 8TH FLOOR CAFETERIA	8:27 AM	11:44 AM	197	9.5	9.5	7.5	1271.8		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [illegible]	JD	2/13/02	16:15
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RRiy	2/13/02	17:20
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: [illegible]

27. Result To: ____
Beeper/Phone #'s ____

28. Comments:

WHITE - File **YELLOW** - Client/Report **PINK** - Lab **GOLDENROD** - Field

NY-1 (1/00)

CITY_21MC100_010190692