NYC 9/11 Public Portal Document

# Oil Sample Analysis Results

Oil and fluids throughout machine have been sampled and sent to K.O.W.A. (Komatsu Oil Wear Analysis) laboratory for analysis. The results are as follows with copies of each lab sample analysis attached:

**Engine:** Analysis indicates acceptable conditions

**Hydraulic System:** Analysis indicates acceptable conditions

**Swing Gearbox:** Analysis indicates satisfactory conditions

**Final Drives:**

**Right:** *Analysis indicates abnormal conditions! See attached report*

**Left:** *Analysis indicates abnormal conditions! See attached report*

04.023874

CITY_21MC100_0011107407

NYC-WTC_000419214