ATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

6303 45/50 69590 69639

Page 1 of 7

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYCSCA	I.S. 89-M	21203-059	ZB Kowalski / [illegible]	[illegible]
	2a. Project Address: 201 Warren St.	3a. Task # 01	4a. Air Sampler: ZB Kowalski / [illegible]	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
1-10-02	6th FLOOR	Cassette/Filter Manufacture _____ Lot # _____	Cassette/Filter Manufacture _____ Lot # 1358	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
01				Field Blank OPEN 30sec + close									
02				Field Blank OPEN 30sec + close									
03		X		6th Floor Corridor @ entrance to Boiler Room	15:35	19:05	210	9.0	9.0	9.0	1890		
04		X		6TH FLOOR BOILER ROOM 10 FT. FROM ENTRANCE	15:36	18:06	210	9.0	9.0	9.0	1890		
05		X		6TH FL. BOILER ROOM BY WATER CHILLER	15:37	19:08	211	9.0	9.0	9.0	1899		
06		X		6TH FLOOR MECH. ROOM @ ENTRANCE	15:38	19:09	211	9.0	9.0	9.0	1899		
07		X		6TH FLOOR MECH. ROOM BY LADDER TO 2ND LEVEL	15:39	19:11	212	9.0	9.0	9.0	1908		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]		1-10-02	
II [signature]	[signature]	1/11/02	5:30am
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: [signature]	1/11/02	8:00
b. QC By: [signature]		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: [signature]

27. Result To: [signature]
Beeper/Phone #'s 1800-079737 # 11852

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY 1 (1/01)

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

6303

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client	2. Project Name	3. Project #	4. Project Monitor	4c. Rotameter Number
NYCSCA	FCFSM	2150.002.02	2B Kowalski / T. Scarcella	#1000
	2a. Project Address: 201 Warren St.	3a. Task # 01	4a. Air Sampler: 2B Kowalski / T. Scarcella	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:	
1-10-02	5th Floor	Cassette/Filter Manufacture: Lot #:	Cassette/Filter Manufacture: Lot #: 13.58	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
08		X		Inside Room #501	1545	1911	209	9.0	9.0	9.0	1881		
09		X		FW Corridor outside Room #506 & Elevators	1546	1915	209	9.0	9.0	9.0	1881		
10		X		Inside Room #510	1548	1917	209	9.0	9.0	9.0	1881		
11		X		Inside Exit #2	1550	1918	208	9.0	9.0	9.0	1872		
12		X		FW Corridor by Room #506	1551	1920	209	9.0	9.0	9.0	1881		
12A		X		Inside Room #506	1552	1921	209	9.0	9.0	9.0	1881		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I			1-10-02	
II		TD	1/11/02	5:20
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC-TEM	23. Date:	24. Time:
a. Analyzed By: RL	1/11/02	8:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Dennis Hardy

27. Result To: Dennis Hardy
Beeper/Phone #'s 1800 [illegible]

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

01/28/2002 16:43 FAX 212 353 8308 ATC 010
CITY_21MC100_003205799
NYC-WTC_000419673

01/28/2002 16:43 FAX 212 353 8308 ATC 011

ATC ASSOCIATES INC.

6303

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 9

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYCSCA	PS 89M	21203.089	Z.B. Kowalski / J. Stanzione	NC AP
	2a. Project Address: 201 Warren St	3a. Task # 01	4a. Air Sampler: Z.B. Kowalski / J. Stanzione	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:		
1-10-02	Library 5th FL	Cassette/Filter Manufacture _____ Lot # _____	Cassette/Filter Manufacture _____ Lot # 1358	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA	f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
13		X		Inside Library North Side	1555	1922	207	9.0	9.0	9.0	1863.		
14		X		Inside Library, Conference Room # 517	1556	1923	207	9.0	9.0	9.0	1863.		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]		1/10/02	
II	JD	1/11/02	5:30 pm
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: RKing	1/11/02	8:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Remi Lanchy

27. Result To: 1600 FOI 9232 # 1881
Beeper/Phone #'s Remi Lanchy

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

VATC ASSOCIATES INC. 6302

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other ____

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
Dycca	PS 89	2103-089	ZB Environ / T. Connelly	41266
	2a. Project Address: 201 Warren ST.	3a. Task # 01	4a. Air Sampler: ZB Environ / T. Connelly	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture ____ Lot # ____	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture ____ Lot # 135B	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other
1-10-02	4th Floor			

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
15		N		Inside Room # 401	1600	1925	205	9.0	9.0	9.0	1845		
16		E		Corridor by Room # 401	1601	1926	205	9.0	9.0	9.0	1845		
17		S		Inside Room # 401	1602	1927	205	9.0	9.0	9.0	1845		
18		W		Corridor in Front of Room 426	1603	1928	205	9.0	9.0	9.0	1845		
19		C		Inside Room # 428	1604	1929	205	9.0	9.0	9.0	1845		
20		F		Inside Stairwell # 1	1604	1931	206	9.0	9.0	9.0	1854		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I		1-10-02	
II	TD	1/10/02	1:30
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: [illegible]	1/11/02	8:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Dan Hendy

27. Result To: Dan Hendy
Beeper/Phone #s/Fax #s: [illegible]

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field NY-1 (1/01)

01/28/2002 16:44 FAX 212 353 8308 ATC 012
CITY_21MC100_003205801
NYC-WTC_000419675

NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

ATC ASSOCIATES INC. 6303

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor	4c. Rotameter Number:
NYC SCA	PS 89(M)	02205.039	K. Yonkoski / P. Sanchez	NA
	2a. Project Address: 201 WARREN ST. NY NY	3a. Task #	4a. Air Sampler: K. Yonkoski / P. Sanchez	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:	
1-10-02	2nd FLOOR	Cassette/Filter Manufacture:	Cassette/Filter Manufacture:	a. ☐ Background	c. ☐ Abatement
		Lot #:	Lot #: 1558	b. ☐ Pre-Abate	d. ☐ Post-Abate
				e. ☐ OSHA	f. ☐ Environmental
					g. ☒ Ambient
					h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. f/CC
				Field Blank									
				Field Blank									
21		u		Inside Room # 301	1610	1935	205	9.0	9.0	9.0	1845		
22		h		Inside STAIRWELL # 3	1611	1936	205	9.0	9.0	9.0	1845		
23		y		Inside Room # 304	1613	1937	204	9.0	9.0	9.0	1836		
24		h		Corridor adj to room # 304	1614	1938	204	9.0	9.0	9.0	1836		
25		jj		Inside Gym, North side	1616	1940	204	9.0	9.0	9.0	1836		
26		X		Inside Gym South side	1617	1942	205	9.0	9.0	9.0	1845		
27		/		Inside Room # 326	1618	1943	205	9.0	9.0	9.0	1845		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I			1/10/02	
II		JD	1/10/02	1:30
III				

LAB INFORMATION (ATC ELAP # 10379, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: RKing	1/10/02	8:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: P. SANCHEZ

27. Result To: P. SANCHEZ
Beeper/Phone #'s:

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field NY-1 (1/01)

01/28/2002 16:44 FAX 212 353 8306 ATC 013

CITY_21MC100_003205802

NYC-WTC_000419676

ATC ASSOCIATES INC

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

6303

Page 6 of 9

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC SCA	PS 89 M	21202-089	J.B. Kowalski / J. Scarella	
	2a. Project Address: 201 Warren St.	3a. Task #: 01	4a. Air Sampler: J.B. Kowalski / J. Scarella	HPAC

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
1-10-02	3rd FL 200 R - 2nd FL 00 R	Cassette/Filter Manufacture _____ Lot # _____	Cassette/Filter Manufacture _____ Lot # 1358	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
28		Y		In Corridor Next To Room # 326 3rd FL	1619	1944	205	9.0	9.0	9.0	1845		
29		Y		Inside Room # ~~[illegible]~~ 202 2nd FL	1626	1949	203	9.0	9.0	9.0	1827		
30		Y		Corridor Adj To Room # 202	1627	1950	203	9.0	9.0	9.0	1827		
31		Y		Inside Room # 204	1628	1952	204	9.0	9.0	9.0	1836		
32		Y		Inside General Offices	1629	1953	204	9.0	9.0	9.0	1836		
33		Y		Auditorium - Stage West	1630	1955	205	9.0	9.0	9.0	1845		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]		1-10-02	
II	JD	1/10/02	[illegible]
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: RRLy	1/12	8:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: Rein Sarely

27. Result To: Rein Sarely
Beeper/Phone #'s 1600 8074 177th 11852

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

01/28/2002 16:44 FAX 212 353 8306 ATC 015

ATC ASSOCIATES INC.

6303

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 7 of 9

TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client:	2. Project Name: FS 69 M	3. Project #: 2305-69	4. Project Mon'tor: [illegible]	4c. Rotameter Number:
NYC SCA	2a. Project Address: 101 WARREN ST. NY NY	3a. Task #:	4a. Air Sampler: [illegible]	[illegible]

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
1-10-02	2nd FLOOR	Cassette/Filter Manufacture: ___ Lot #: ___	Cassette/Filter Manufacture: ___ Lot #: 1358	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location: 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock): 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.): 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
34 ~~08~~		X		Auditorium - East side	1631	1957	206	9.0	9.0	9.0	1857.		
35 ~~09~~		X		Stairwell #2	1632	1959	207	9.0	9.0	9.0	1863.		
36 ~~10~~		X		Corridor Adj. To Room 228	1633	2000	207	9.0	9.0	9.0	1863.		
~~11~~													
~~12~~													

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I [signature]		1-10-02	
II	[signature]	1/10/02	5:30
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: [signature]	1-10-02	8:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: P. Sanchez

27. Result To: P. Sanchez
Beeper/Phone #'s: ___

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

NYC 9/11 Public Portal Document

VATC ASSOCIATES INC

6303

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other ____

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor:	4c. Rotameter Number:
NYC DCA	PI 8911	2303-89	Howard Garrett	HP 110
	2a. Project Address: 201 WARREN ST NY NY	3a. Task #	4a. Air Sampler: Howard Garrett	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture ____ Lot # ____	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture ____ Lot # 13583	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA	f. ☐ Environmental g. ☒ Ambient h. ☐ Other
1-10-02	1ST FLOOR				

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
37		X		Kitchen -	1635	2002	207	9.0	9.0	9.0	1863.		
38		X		Kitchen - Serving Area	1636	2003	207	9.0	9.0	9.0	1863.		
39		X		Cafeteria	1637	2005	208	9.0	9.0	9.0	1877.		
40		X		Cafeteria	1638	2006	208	9.0	9.0	9.0	1872.		
41		X		Stairwell #3	1639	2007	208	9.0	9.0	9.0	1872		
42		X		corridor 1ST FL by stairwell #3	1640	2008	208	9.0	9.0	9.0	1872		

CHAIN OF CUSTODY

	18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I			1-10-02	
II		JR	1/10/02	17:30
III				

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: BRay	1/10/02	8:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: R. SANCHEZ

27. Result To: R. SANCHEZ
Beeper/Phone #'s ____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

01/28/2002 16:44 FAX 212 353 8308 ATC 016

CITY_21MC100_003205805

NYC-WTC_000419679

NYC 9/11 Public Portal Document

VATC ASSOCIATES INC.

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

6303

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client:	2. Project Name	3. Project #	4. Project Monitor	4c. Rotameter Number:
NYC EDC	7 WTC BLDG	2003.639	K. Kennedy / J. Spencer	HP 110
	2a. Project Address: 31 WARREN ST. NY NY	3a. Task #	4a. Air Sampler: K. Kennedy / J. Spencer	

5. Date:	6. Abatement Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:	
1-10-02	15th Floor	Cassette/Filter Manufacturer: _____ Lot #: _____	Cassette/Filter Manufacturer: _____ Lot #: 1350	a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
43		X		Corridor 15th Floor By North exit	1041	2010	209	9.0	9.0	9.0	1881		
44		X		Room #1281 (inside)	1042	2011	209	9.0	9.0	9.0	1881		
45		X		Inside Room #1328	1044	2012	208	9.0	9.0	9.0	1872		
46		X		Inside Room #134	1045	2013	208	9.0	9.0	9.0	1872		
47				OPEN 30sec + close	—	—	—	—	—	—	—		
48				OPEN 30sec + close	—	—	—	—	—	—	—		
49				Sealed BLANK	—	—	—	—	—	—	—		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I - [signature]		1-10-02	
II -	TD	1/11/02	5:30
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC - TEM	23. Date:	24. Time:
a. Analyzed By: RRM	1/11/02	8:00
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager: P. SANCHEZ

27. Result To: P SANCHEZ
Beeper/Phone #'s: _____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1/01)

01/28/2002 16:45 FAX 212 353 8306 ATC 017

CITY_21MC100_003205806

NYC-WTC_000419680