ATHENICA
ENVIRONMENTAL SERVICES INC.
Tel: (718) 784-7490
Fax: (718) 784-4085

CLIENT: SCA
SITE: Economics A.S. M
PROJECT NO. (ATHENICA FILE#): 01-0613
DATE: 11 12ST 01
PURPOSE OF MONITORING: AREA SAMPLING
TECHNICIAN: Glopez, J. Garoutsos
CASETTE SIZE: 25 mm
LOT#:
ROTOMETER#: GL-001
BATCH#: 01-11-084
TYPE-OF-RESPIRATOR:
PROJECT MANAGER: B. Bellos
AREAS OF ABATEMENT: 5th, ~~6th~~ 4th, 3rd Floors
TYPE-OF-REMOVAL: Dust Control

PCM ✓ TEM ☐
CHECK ONLY ONE BOX

Background ☐ Pre-Abatement ☐ Durrings ☐ Finals ✓ Others (Explain)
(CHECK ONLY ONE BOX)

SAMPLE ID#	LOCATION	TYPE *	PUMP	TIME IN	TIME OUT	TOTAL MIN.	FLOW BEFORE	FLOW AFTER	FLOW AVERAGE	VOLUME	FIBERS/ FIELD	FIBERS/ C.C.
1	5th Fl In Rm # 510 Center	IFNL		1114	1244	90	14	14	14	1260	07/100	<.01
2	↓ ↓ # 509 Center			1115	1245	90	14	14	14	1260	04/100	<.01
3	5th Fl Corridor by Rm # 507			1116	1246	90	14	14	14	1260	06/100	<.01
4	In Rm # 508 Center			1117	1247	90	14	14	14	1260	09/100	<.01
5	In Rm # 505 Center			1118	1248	90	14	14	14	1260	11/100	<.01
6	In SE Computer Rm Center			1120	1250	90	14	14	14	1260	08/100	<.01
7	S. Computer Rm Center			1122	1252	90	14	14	14	1260	05/100	<.01
8	In Stairwell # B			1123	1253	90	14	14	14	1260	02/100	<.01
9	4th Fl. in Rm # 400 Center			1125	1255	90	14	14	14	1260	03/100	<.01
10	↓ ↓ # 409			1127	1257	90	14	14	14	1260	02/100	<.01
11	In Stairwell A			1128	1258	90	14	14	14	1260	06/100	<.01
12	In Rm # 408 Center			1130	1300	90	14	14	14	1260	1.5/100	<.01

BGA - Backround
PRE - Preabatement
IWA - Inside Work Area
OB - Outside Building
ICR - Inside Clean Room
NGAE - Negative Air Exhaust
OWA - Outside work area
OTH - Other
OFNL Outside Finals
IFNL - Inside Finals

CHAIN OF CUSTODY RECORD

RELINQUISHED BY:	Lopez /	DATE:	11/25/01	TIME:	19:30
RECEIVED BY:	[signature]	DATE:	11/25/01	TIME:	19:30
ANALYST:	[signature]	DATE:	11/25/01	TIME:	19:55

LABORATORY ACCREDITATION:
NVLAP# 101958 ELAP# 10955 METHOD: NIOSH 7400

WHITE-FILE/LAB YELLOW-CLIENT/REPORT PINK-FIELD

11/25/2001 21:02 FAX 718 784 4085
CITY_21MC100_003076593
006

NYC 9/11 Public Portal Document

ATHENICA
ENVIRONMENTAL SERVICES INC.
Tel: (718) 784-7490
Fax: (718) 784-4085

☑007

CLIENT: SCA
SITE: Economics H.S. M
PROJECT NO. (ATHENICA FILE#): 01-0613
DATE: 11.12&1 01
PURPOSE OF MONITORING: AREA SAMPLING
TECHNICIAN: G Lopez, J. Garoufalos
CASETTE SIZE: 25 mm
LOT#:
ROTOMETER#: G L-001
BATCH#: 01-11-084
TYPE-OF-RESPIRATOR:
PROJECT MANAGER: B. Bellas
AREAS OF ABATEMENT: 5th, 4th 3rd Floors
TYPE-OF-REMOVAL: Dust Control

PCM [✓] TEM [ ]
CHECK ONLY ONE BOX

Background [ ] Pre-Abatement [ ] Durrings [ ] Finals [✓] Others (Explain) [ ]
(CHECK ONLY ONE BOX)

SAMPLE ID#	LOCATION	TYPE *	PUMP	TIME IN	TIME OUT	TOTAL MIN.	FLOW BEFORE	FLOW AFTER	FLOW AVERAGE	VOLUME 1260	FIBERS/cc FIELD	FIBERS/cc C.C.
13	4th fl Elev Rm #407 Center	IFNL		1132	1302	90	14	14	14	1302	02/100	<.01
14	" #406 Center			1134	1304	90	14	14	14	1260	08/100	<.01
15	" #405 Center			1137	1307	90	14	14	14	1260	09/100	<.01
16	Corridor In Front East A			1138	1308	90	14	14	14	1260	06/100	<.01
17	In Rm #404 Center			1140	1310	90	14	14	14	1260	03/100	<.01
18	In Corridor by Stairway B			1141	1311	90	14	14	14	1260	04/100	<.01
19	3rd fl in Stairwell B			1146	1316	90	14	14	14	1260	07/100	<.01
20	In Rm #303 Center			1148	1318	90	14	14	14	1260	05/100	<.01
21	In S.E. Rm Center			1149	1319	90	14	14	14	1260	09/100	<.01
22	In Rm #305			1150	1320	90	14	14	14	1260	04/100	<.01
23	" #306			1151	1321	90	14	14	14	1260	06/100	<.01
24	" #307			1152	1322	90	14	14	14	1260	08/100	<.01

BGA - Backround
PRE - Preabatement
IWA - Inside Work Area
OB - Outside Building
ICR - Inside Clean Room
NGAE - Negative Air Exhaust
OWA - Outside work area
OTH - Other
OFNL Outside Finals
IFNL - Inside Finals

CHAIN OF CUSTODY RECORD

RELINQUISHED BY:	Lopez	DATE:	11/25/01	TIME:	19:30
RECEIVED BY:		DATE:	11/25/01	TIME:	19:30
ANALYST:		DATE:	11/25/01	TIME:	19:55

LABORATORY ACCREDITATION:
NVLAP# 101958 ELAP# 10955 METHOD: NIOSH 7400

WHITE-FILE/LAB YELLOW-CLIENT/REPORT PINK-FIELD

11/25/2001 21:02 FAX 718 784 4085

CITY_21MC100_00307659 4

NYC-WTC_000429512