NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	07-15-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS
SAMPLED BY:	Client
SAMPLE DATE	07-14-02
DATE RECEIVED:	07-14-02
DATE ANALYZED:	07-14-02
SAMPLE MEDIA:	Dust Wipe Sample
ANALYSIS REQUIRED:	Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-01	20362	Room 1001 East Side Univent Back Wall	<9.0	9.0
W-02	20362	Room 1001 South Side Left Univent Back Wall	<9.0	9.0
W-03	20362	Room 1001 South Side Right Univent Back Wall	<9.0	9.0
W-04	20362	Room 1007 South Side Left Univent Back Wall	<9.0	9.0
W-05	20362	Room 1007 South Side Middle Univent Back Wall	<9.0	9.0
W-06	20362	Room 1007 South Side Right Univent Back Wall	<9.0	9.0
W-07	20362	Field Blank	<9.0	9.0
W-08	20362	Field Blank	<9.0	9.0

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg

SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

NYC-WTC_000430734