NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

**REPORT DATE:** 07-18-02

**CLIENT:** Taylor Environmental Group, Inc.

**PROJECT NAME:** SCA/Stuyvesant HS
345 Chambers St., 9th Floor

**SAMPLED BY:** Client

**SAMPLE DATE** 07-17-02
**DATE RECEIVED:** 07-17-02
**DATE ANALYZED:** 07-17-02

**SAMPLE MEDIA:** Air Samples
**ANALYSIS REQUIRED:** Method NIOSH 7082

ANALYSIS RESULTS

| SAMPLE ID | BATCH NO. | SAMPLE DESCRIPTION | LEAD CONCENTRATION ($\mu g/m^3$) | DETECTION LIMIT ($\mu g/m^3$) |
|---|---|---|---|---|
| 01 | 20444 | Inside Classroom 938 Near Entrance to Hallway | <3.1 | 3.1 |
| 02 | 20444 | Inside Classroom 940 Near Entrance to Hallway | <3.1 | 3.1 |
| 03 | 20444 | Inside Classroom 939 Near Entrance to Hallway | <3.1 | 3.1 |
| 04 | 20444 | Inside Classroom 935 Near Entrance to Hallway | <3.1 | 3.1 |
| 05 | 20444 | Inside Classroom to Hallway Near Entrance to Hallway 936 | <3.1 | 3.1 |
| 06 | 20444 | Inside Classroom 931 Near Entrance to Hallway | <3.1 | 3.1 |
| 07 | 20444 | Inside Classroom 927 Near Entrance to Hallway | 8.7 | 3.1 |
| 08 | 20444 | Inside Classroom 911 Near Entrance to Hallway | <3.1 | 3.1 |
| 09 | 20444 | Inside Classroom 1010 Near Entrance to Hallway | <3.1 | 3.1 |
| 10 | 20444 | Inside Classroom 926 Near Entrance to Hallway | 4.2 | 3.1 |
| 11 | 20444 | Inside Classroom 938 Near Entrance to Hallway | 4.9 | 3.1 |
| 12 | 20444 | Inside Classroom 940 Near Entrance to Hallway | 5.4 | 3.1 |
| 13 | 20444 | Inside Classroom 939 Near Entrance ot Hallway | 5.6 | 3.1 |
| 14 | 20444 | Inside Classroom 936 Near Entrance to Hallway | 3.7 | 3.1 |
| 15 | 20444 | Inisidc Classroo 902 Near Entrance to Hallway | 4.3 | 3.1 |
| 16 | 20444 | Inside Classroom 911 Near Entrance to Hallway | 15.5 | 6.0 |

CONFIDENTIAL, CITY_21MC100_003475030
SUBJECT TO PROTECTIVE ORDER NO. 2, SEPT. 2008

NYC-WTC_000430748

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

| | | | | |
|---|---|---|---|---|
| 17 | 20444 | Inside Classroom 1010 Near Entrance to Hallway | 7.3 | 6.6 |
| 18 | 20444 | Inside Classroom 926 Near Entrance to Hallway | 11.5 | 7.5 |
| 19 | 20444 | Field Blank | <1.5 µg | 1.5 µg |
| 20 | 20444 | Field Blank | <1.5 µg | 1.5 µg |
| 21 | 20444 | Field Blank | <1.5 µg | 1.5 µg |

NOTE 1:
THE REPORTING LIMIT (RL) IS 3.0 µg
NOTE 2:
At the present time there are no regulatory levels or requirements for indoor airborne lead in area samples. However, OSHA has established an action level of 30 $\mu g/m^3$ and a permissible exposure level (PEL) of 50 $\mu g/m^3$ for personal samples.
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: HCH

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879). (AIHA #100229).



NYC-WTC_000430749