NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-22-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY
8th,10th Floors

PROJECT NUMBER: M477-15217-29881

SAMPLED BY: Client

SAMPLE DATE 07-19-02
DATE RECEIVED: 07-20-02
DATE ANALYZED: 07-20-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
W-01	20511	Rm #1017A Top Unit Vent (Composit Sample)	<9.0	9.0
W-02	20511	Rm #1017A Bottom Unit Vent South Side Back Wall	<9.0	9.0
W-03	20511	Rm #801 East Side Unit Vent Back Wall	<9.0	9.0
W-04	20511	Rm #807 South Side Unit Vent Back Wall	<9.0	9.0
W-05	20511	Rm #809 South Side Unit Vent Back Wall	<9.0	9.0
W-06	20511	Rm #811 South Side Right Unit Vent Back Wall	<9.0	9.0
W-07	20511	Rm #811 South Side Middle Unit Vent Back Wall	<9.0	9.0
W-08	20511	Rm #811 South Side Left Unit Vent Back Wall	<9.0	9.0
W-09	20511	Rm #826 North Side Unit Vent Back Wall	9.8	9.0
W-10	20511	Rm #803 South Side Right Unit Vent Back Wall	12.2	9.0
W-11	20511	Rm #803 South Side Middle Unit Vent Back Wall	<9.0	9.0
W-12	20511	Rm #803 South Side Left Unit Vent Back Wall	<9.0	9.0
W-13	20511	Rm #803 East Side Unit Vent Back Wall	<9.0	9.0
W-14	20511	Field Blank	<9.0 µg	9.0 µg

NYC-WTC_000430849

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

W-15	20511	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000430850