NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-24-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 07-23-02
DATE RECEIVED: 07-23-02
DATE ANALYZED: 07-23-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
LW-01	20599	Rm 601 East Side Unitvent Rear	18.3	9.0
LW-02	20599	Rm 615 East Side Unitvent Rear	24.4	9.0
LW-03	20599	Rm 615 South Side Unitvent A Rear	30.1	9.0
LW-04	20599	Rm 615 South Side Unitvent B Rear	<9.0	9.0
LW-05	20599	Rm 615 South Side Unitvent C Rear	<9.0	9.0
LW-06	20599	Rm 615 South Side Unitvent D Rear	15.5	9.0
LW-07	20599	Rm 615 South Side Unitvent E Rear	11.7	9.0
LW-08	20599	Rm 615 Souht Side Unitvent F Rear	13.3	9.0
LW-09	20599	Rm 615 South Side Unitvent G Rear	<9.0	9.0
LW-10	20599	Rm 615 South Side Unitvent H Rear	<9.0	9.0
LW-11	20599	Rm 615 South Side Unitvnet I Rear	<9.0	9.0
LW-12	20599	Rm 615 South Side Unitvent J Rear	<9.0	9.0
LW-13	20599	Rm 615 South Side Unitvent K Rear	<9.0	9.0
LW-14	20599	Rm 629/635 South Side Left Center Unitvent Rear	<9.0	9.0
LW-15	20599	Rm 629/635 South Side Left Center Unitvent Rear	<9.0	9.0

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

LW-16	20599	Rm 829/635 South Side Right Center Unitvent Rear	<9.0	9.0
LW-17	20599	Rm 629/635 South Side Right Unitvent Rear	<9.0	9.0
LW-18	20599	Rm 639 South Side Left Unitvent Rear	<9.0	9.0
LW-19	20599	Rm 639 South Side Right Unitvent Rear	<9.0	9.0
FBL-1	20599	Field Blank	<9.0 µg	9.0 µg
FBL-2	20599	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².
NOTE 3:
Blank units are in µg

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000430872