TAYLOR ENVIRONMENTAL GROUP

DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

#04 11 C

PAGE 1 OF 1

TECHNICIAN: Gary McKenzie	CLIENT: NYC SCA	SITE ADDRESS: Stuyvesant H.S. 345 Chambers St. N.Y., N.Y.	DATE SUBMITTED: 8/23/02
DATE SAMPLED: 8/23/02	CONTACT: HAMID SAVOJ.	WORK AREA: 9th Floor	DATE LOGGED:
ROTOMETER NO.: L-21	PROJECT NO.: M477-15217-29887	PROJECT MANAGER: G. Taylor	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/CC
9-L1		IWA ☑ OWA ☐ 9th Floor Corridor ADJ. TO ROOM 902	4/4	0005	0416	251	4	1004				
9-L2		IWA ☑ OWA ☐ 9th Floor Corridor ADJ. TO ROOM C923	4/4	0007	0418	251	4	1004				
9-L3		IWA ☑ OWA ☐ 9th Floor Corridor ADJ. TO ROOM 940	4/4	0009	0421	252	4	1008				
FBL-1		IWA ☐ OWA ☐ Field Blank										
FBL-2		IWA ☐ OWA ☐ Field Blank										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										

RELINQUISHED TO TEG DROP BOX (SIGNATURE): [signature]	DATE: 8.23.02	TIME: 6:10	RECEIVED FROM TEG DROP BOX (SIGNATURE): [signature]	DATE: 08-23-02	TIME: 6:30 am
RELINQUISHED BY: (SIGNATURE): [signature]	DATE: 8/23	TIME: 0545	RECEIVED BY: (SIGNATURE):	DATE:	TIME:
ANALYST: (SIGNATURE): [signature]	DATE: 8/23/02	TIME: 9:00 am	COMMENTS: 3 HR TAT FAX TO: 212-406-2535 & 516-358-1780		

CIRCLE: PCM TEM BGRD PRE DURING POST OSHA OTHER LEAD

LOT #

FILTER MANUFACTURER

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 08-23-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
9th Floor

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE 08-23-02
DATE RECEIVED: 08-23-02
DATE ANALYZED: 08-23-02

SAMPLE MEDIA: Air Samples
ANALYSIS REQUIRED: Method NIOSH 7082

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/m^3$)	DETECTION LIMIT ($\mu g/m^3$)
9-L1	21416	9th Floor Corridor Adj. To Rm 902	<1.5	1.5
9-L2	21416	9th Floor Corridor Adj. To Rm C923	<1.5	1.5
9-L3	21416	9th Floor Corridor Adj. To Rm 940	<1.5	1.5
FB1	21416	Field Blank	<1.5 µg	1.5 µg
FB2	21416	Field Blank	<1.5 µg	1.5 µg6

NOTE 1:
THE REPORTING LIMIT (RL) IS 3.0 µg
NOTE 2:
At the present time there are no regulatory levels or requirements for indoor airborne lead in area samples. However, OSHA has established an action level of 30 $\mu g/m^3$ and a permissible exposure level (PEL) of 50 $\mu g/m^3$ for personal samples.
NOTE 3:
Blank units are in µg

NYC-WTC_000430965

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).